

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE	1	
FILE	1	✓
U.S.G.S.		
LAND OFFICE		
OPERATOR	1	

FFB 26 1980

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO FILL OR TO OPEN AN HOLE BACK TO THE SERVICE OFFICE

1. ☐ OIL WELL ☒ GAS WELL OTHER-		7. Unit Agreement Name
2. Name of Operator Northern Natural Gas Company ✓		6. Farm or Lease Name State LG-4216
3. Address of Operator 403 Wall Towers West, Midland, Texas 79701		9. Well No. 1
4. Location of Well: UNIT LETTER <u>F</u> <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM <u>West</u> LINE, SECTION <u>36</u> TOWNSHIP <u>18S</u> RANGE <u>28E</u> N.M.P.M.		10. Field and Pool, or Wildcat N. Turkey Track, Morrow
15. Elevation (Show whether DF, RT, GR, etc.) 3414.2' GR		12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
☐ (a) Obtain a copy of the record	☐ (a) Obtain a copy of the record
☐ (b) Obtain a copy of the record	☐ (b) Obtain a copy of the record
☐ (c) Obtain a copy of the record	☐ (c) Obtain a copy of the record
☐ (d) Obtain a copy of the record	☐ (d) Obtain a copy of the record
☐ (e) Obtain a copy of the record	☐ (e) Obtain a copy of the record
☐ (f) Obtain a copy of the record	☐ (f) Obtain a copy of the record
☐ (g) Obtain a copy of the record	☐ (g) Obtain a copy of the record
☐ (h) Obtain a copy of the record	☐ (h) Obtain a copy of the record
☐ (i) Obtain a copy of the record	☐ (i) Obtain a copy of the record
☐ (j) Obtain a copy of the record	☐ (j) Obtain a copy of the record
☐ (k) Obtain a copy of the record	☐ (k) Obtain a copy of the record
☐ (l) Obtain a copy of the record	☐ (l) Obtain a copy of the record
☐ (m) Obtain a copy of the record	☐ (m) Obtain a copy of the record
☐ (n) Obtain a copy of the record	☐ (n) Obtain a copy of the record
☐ (o) Obtain a copy of the record	☐ (o) Obtain a copy of the record
☐ (p) Obtain a copy of the record	☐ (p) Obtain a copy of the record
☐ (q) Obtain a copy of the record	☐ (q) Obtain a copy of the record
☐ (r) Obtain a copy of the record	☐ (r) Obtain a copy of the record
☐ (s) Obtain a copy of the record	☐ (s) Obtain a copy of the record
☐ (t) Obtain a copy of the record	☐ (t) Obtain a copy of the record
☐ (u) Obtain a copy of the record	☐ (u) Obtain a copy of the record
☐ (v) Obtain a copy of the record	☐ (v) Obtain a copy of the record
☐ (w) Obtain a copy of the record	☐ (w) Obtain a copy of the record
☐ (x) Obtain a copy of the record	☐ (x) Obtain a copy of the record
☐ (y) Obtain a copy of the record	☐ (y) Obtain a copy of the record
☐ (z) Obtain a copy of the record	☐ (z) Obtain a copy of the record

PERFORM REMEDIAL WORK	☐	PLUG AND ABANDON	☐	REMEDIAL WORK	☐	ALTERING CASING	☒
TEMPORARILY ABANDON	☐			COMMENCE DRILLING OPNS.	☐	PLUG AND ABANDONMENT	☐
PULL OR ALTER CASING	☐	CHANGE PLANS	☐	CASING TEST AND CEMENT JOB	☐		
OTHER _____	☐			OTHER	<u>Completion, treating & testing</u>		☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12-31-79 Moved in completion unit & rig up. Installed tubing head.

1-1-80 TIH w/4-3/4" bit & 5-1/2" csg scraper. Circ & cond brine wtr for completion fluid. Spotted 250 gals 10% MSA perforating acid from 11,014 to 10,764'.

1-2-80 Welex ran junk basket & gauge ring to 11,060'. Bond log failed.

1-3-80 Welex ran GR, CCL, CBL logs. Set Otis "WB" pkr w/8' pup & "N" nipple @ 10,860'.

1-4-80 Ran 2-3/8" tbg w/Otis "Perma Trieve" pkr. Tested tbg to 6000 psi. Set pkr @ 10,676'. NU tree.

1-7-80 Welex perforated (0.29") 1 JSPF 10,956-10,962 & 10,971-10,979' (total 16 shots).

1-8-80 16 hr SITP 1600 psig. Blew down in 30 mins. Gas TSTM.

1-9-80 Dowell acidized w/3500 gals 7-1/2% MSA w/1000 SCFN₂/bbl. Rec load & flwd well to burning pit. FTP "0" gauge TSTM. Set plug in "N" nipple @ 10,878'.

1-10-80 CRC Wireline perforated (0.29") 1 JSPF 10,812-10,827' (16 holes). No flow.

1-11-80 Dowell acidized w/3500 gals 7-1/2% MSA w/1000 SCFN₂/bbl. Flwd load back & swbd to 10,660'. Gas TSTM.

1-12-80 Hung dual pressure bombs @ 10,680'. Well SI for BHP buildup.

1-16-80 SITP (96 hrs) 3450 psig. Pulled BHP bombs. SI waiting on buildup analysis.

1-29-80 Halliburton fraced perfs 10,812-10,827' w/717 bbls gelled KCL wtr + 26,000# 20-40 sd + 16,000# 20-40 super props + CO₂. Flowed back 250 bbls load.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED E. H. Hunt TITLE District Engineer DATE 2-25-80

WA Gussett

SUPERVISOR, DISTRICT II

DATE FEB 29 1980

CONDITIONS OF APPROVAL, IF ANY: