

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE	1	
FILE	1	/
U.S.G.S.		
LAND OFFICE		
OPERATOR	/X	

RECEIVED
NEW MEXICO OIL CONSERVATION COMMISSION

FEB 15 1983

O.C.D.
ARTESIA OFFICE

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-83

5a. Indicate Type of Lease	State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	L-4379

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Monsanto Oil Company	8. Farm or Lease Name SRC "35" State
3. Address of Operator 1300 One Midland National Center, Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER I 2310 FEET FROM THE south LINE AND 330 FEET FROM east LINE, SECTION 35 TOWNSHIP 185 RANGE 27E.	10. Field and Pool, or Wildcat Artesia Queen (Grayburg)
15. Elevation (Show whether DF, RT, GR, etc.) 3549' KB	12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASINGS <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

To plug and abandon well.

1. Set CIBP @ 1550' cap w/35' cement. RTR & SEP. w/ 35' CIBP to top of rtr
2. Circulate hole w/9 ppg mud.
3. Spot 25 sx plug @ 425'.
4. Set 20 sx plug @ surface.

Work will start approximately March 15, 1983.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jane Chisholm TITLE Regional Engineer DATE 2/11/83

APPROVED BY W. H. Walker OIL AND GAS INSPECTOR DATE FEB 21 1983

CONDITIONS OF APPROVAL, IF ANY: