

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION

DISTRICT I
P. O. Box 1980 Hobbs, NM 88240

P. O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P. O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd, Aztec, NM 87410

Well APINO.	30-015-23278
5. Indicate Type or Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B-11594-3
7. Lease Name or Unit Agreement Name	TRAVIS 13 STATE
8. Well No.	# 1
9. Pool name or Wildcat	TRAVIS UPPER PENN

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well OIL <input checked="" type="checkbox"/> WELL GAS <input type="checkbox"/> WELL OTHER <input type="checkbox"/>	2. Name of Operator Harvey E. Yates Company	3. Address of Operator P.O. Box 1993, Roswell, NM 88202 1-505-623-6601
4. Well Location Unit Letter <u>F</u> : <u>1,980</u> Feet From The <u>NORTH</u> Line and <u>1,980</u> Feet From The <u>WEST</u> Line Section <u>13</u> Township <u>18S</u> Range <u>28E</u> NMPM <u>EDDY</u> County	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3620' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input checked="" type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER: <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.) SEE RULE 1103

UPON PARTNER APPROVAL WILL LEAVE CANYON & TEST BONE SPRING SAND
SET CIBP @ 9,800' +/- w/ 35' CMT ON TOP. (CURRENT PERFS 9824-40').
SET CIBP @ 8,220' (TOP OF WOLFCAMP) PLUS 35' CMT.
PERF 4 HOLES @ 6631 & CMT 5 1/2" CASING ANNULUS TO APPROX. 3000'. (CMT RET. @ APPROX. 6600')
RUN CORRELATION LOGS. PERF BONE SPRING SAND. ACIDIZE & FRAC IF SHOWS.
RUN PRODUCTION ASSEMBLY. PUT ON PROD.

RECEIVED

MAR 10 1995

OIL CON. DIV.
DIST. 2

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ray F. Nokes TITLE PROD. MGR. / ENGINEER. Date 3/7/95
TYPE OR PRINT NAME RAY F. NOKES TELEPHONE NO. 1-505-623-6601

(This space for State use)

ORIGINAL SIGNED BY TIM W. GUN
DISTRICT MANAGER

Approved by TIM W. GUN Title DISTRICT MANAGER Date MAR 13 1995

Conditions of approval, if any: