REGEIVED

NU OIL COMS. COL. SSION

Drawer DD intocia. My

Form 3160-5 (June 1990)

LUG

UNITED STATES

DEPARTMENT OF THE INTERIOR S BUREAU OF LAND MANAGEMENT

SEP 3 0 1993

FORM APPROVED Budget Bureau No. 1004-0135

Expires: March 31, 1993 5. Lease Designation and Serial No.

THE O15 NA -0/0 907-A 6. If Indian, Allottee or Tribe Name

Conversion to Injection

Dispose Water (Note: Report results of mi

SUNDRY NOTICES AND REPORTS ON WELLS . C. D. Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation
1. Type of Well X Oil		8. Well Name and No. EMPIRE FED. 34 # 1 9. API Well No.
3. Address and Telephone No. P.O. Box 51810 Midland, TX 79710 4. Location of Well (Footage, Sec., T., R., M., or Survey Do SW/NE, SEC. 34, T-18-S, R-29-E 1980 FNL & 1980 FEL		10. Field and Pool, or Exploratory Area 11. County or Parish, State EDDY COUNTY, NM
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REF	
Notice of Intent Subsequent Report	Abandonment Recompletion Plugging Back Casing Repair	Change of Plans New Construction Non-Routine Fracturing Water Shut-Off

Completion or Recompletion Report and Lag form.) 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

OUR PLANS ARE TO DO THE FOLLOWING RECOMPLETION TO THE CISCO LIME.

X Other INTENDED RECOMPLETION

PROPOSED PROCEDURE:

Final Abandonment Notice

- 1. MIRU. BLOW WELL DOWN. NO WH. NU BOP. RELEASE PKR AND POOH W/TBG AND PACKER. RIH W/CMT RETAINER TO 8930', SET RTNR AND ESTABLISH PMP N RATE WITH 2% KCL WATER.
- 2. SQZ WOLFCAMP WITH 100 SXS CLASS H CMT WITH 0.8% FL-20 ADDED. POOH
- 3. RIH W/BIT AND SCRAPERS. DRILL OUT RETAINER AND CMT. TEST SQZ TO 2000 PSI. POOH.
- 4. MIRU WIRELINE CO. PERFORATE CISCO LIME W/3 3/8" CSG GUN AT 9894-9915 (4 SPF, 84 SHOTS). USE GR LOG FOR CORRELATION TO LIMESTONE UNIT MARKED ON THE GR OF THE LATEROLOG.
- 5. RIH WITH TREATING PKR ON 2 3/8" TBG TO +\-9800'. SET PKR. MIRU STIMULATING CO. NU SURFACE LINES AND TEST TO 8000 PSI.
- 6. BREAKDOWN CISCO WITH 2000 GLS OF 15% NEFE HCL ACID AT 6 BPM DOWN 2 3/8" TBG. LOAD AND MONITOR 1500 PSI ON ANNULUS DURING JOB. SPACE OUT 126 7/8" RCNBS. RELEASE PRESSURE AND RDMO STIMULATING CO. SWAB BACK ACID AND TEST WELL.
- 7. AFTER TESTING WELL, KILL IT WITH 2% KCL WATER AND INSTALL PLUNGER LIFT EQUIPMENT.

14. I hereby certify that the foregoing is true and correct Signed DORNA WILLIAMS	Title PRODUCTION ASSISTANT	Detc 7/30/93
(This space for Federal or State office use) Approved by (ORIG. SGD.) JOE G. LARA	Title Petroleum Engineer	Dete9/29/93
Conditions of approval, if any:		