9/1/00		Tubing was on vacuum, casing had slight blow, first run hit fluid @ 6,400', last run fluid level was @ 7,300'. Recovered 120 bbls water.
9/2/00		Tubing on a vacuum, casing had slight blow, first run hit fluid @ 6,500', last run fluid level was @ 7,400'. Recovered 150 bbls water.
9/3	5/00	No report.
Report from Hallwood		
	4/00	 Hallwood PO: Swabbing. SITP -0-, SICP -0 Open csg, have good blow of gas, IFL 5=6400', FFL 7300'. Swabbed 135 bbls H2O, total fluid rec 785 bbls H2O.
9)/5/00	PO: Swabbing. SITP –0-, SICP –0 Swabbed 127 bbls H2O, no gas shows, IFL 6400, FFL 7400, no gas, SI well for night.
	9/6/00	PO: Swabbing. SITP -0-, SICP -10 psi. In FL @ 6800 ft, Final FL @ 7400 ft, No gas - Total fluid rec 2022 bbls - SI well for night.
	9/7/00	PO: Pull bombs. Tbg on vac, SICP 10 psi, continue swabbing, Pro Wireline ran tandem BHP bombs, SI over weekend.
	9/8/00	No report.
	9/9/00	PO: Swabbing. SITP 0, SICP 10 psi. IFL 6600, swabbed 137 bbls wtr, no gas show, total fluid rec 2440 bbls, SI & SD for night.
1	9/10/00	PO: Swabbing. Swabbed 90± bbls wtr, parted sanline, SI well, SITP 0, SICP 10 psi. IFL 6600, swabbed 137 bbls wtr, no gas show, total fluid rec 2440 bbls, SI & SD for night.
	9/11/0	SITP 0, SICP 10 psi. Replaced 8000 ft of sanline on rig, RIH w/overshot on sanline, tag top of fish @ 10250' (SN @ 10270 ft), overshot kept slipping off fish, POOH, SDFN.

_ - -