

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-015-23496
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Rio Penasco OJ Com
8. Well No. 1
9. Pool name or Wildcat Undesignated Atoka
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3485' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER
2. Name of Operator YATES PETROLEUM CORPORATION
3. Address of Operator 105 South Fourth Street - Artesia, NM 88210
4. Well Location Unit Letter J : 1980 Feet From The South Line and 1980 Feet From The East Line Section 34 Township 18S Range 25E NMPM Eddy County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Abandon Wolfcamp & recompleat to Atoka <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-25-95 - Moved in and rigged up pulling unit. Unseat pump. Laid down rods and pump. Released tubing anchor catcher. Nippled up BOP. Picked up 89' of tubing. TOOH with tubing. Tally pipe coming out. Tagged at 8537'.

4-26-95 - TIH with notched collar on tubing. Tagged fill at 8537'. Loaded hole with 20 bbls. Washed down to 8786'. Circulated clean. TOOH with tubing. TIH with 4" packer gun and perforated 8585-8590' with 20 .42" holes. TOOH with wireline. TIH with 5-1/2" 17-20# Uni VI packer with 1.81" XL on/off tool. Nippled down BOP. Set packer at 8536'. Nippled up tree. Swabbed tubing down. Rigged up tree saver and BJ-Western. Break down perforations. Acidized perforations 8585-8590' with 2500 gallons 7-1/2% MS acid with 1000 scf/hd nitrogen. Flow well. Shut in.

4-27-95 - Opened well and flow test. Shut well in. Released well to production department.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Production Clerk DATE 4-30-95
TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505-748-1471

(This space for State Use)

ORIGINAL SIGNED BY TIM W. CUM
DISTRICT II SUPERVISOR

TITLE

DATE

MAY 8 1995