

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED

JUN 1 1 1992

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS O. C. D.

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such proposals

5. Lease Designation and Serial No.

Lc-067132

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Empire 22 Federal

9. API Well No.

SWD #1

10. Field and Pool, or Exploratory Area

11. County or Parish, State

Eddy

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well ☐ Gas Well ☒ Other

2. Name of Operator

I & W, Inc. ✓

3. Address and Telephone No.

P.O. Box 98 - Loco Hills, New Mexico 88255

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Sec 22 T-18-S R-29-E
1980 FSL 1980 FWL

W. K

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- 1) Set 4 1/2 CIBP at 8700' and cap W/35' cement
- 2) Load Hole W/Mud
- 3) Cut and pull 4 1/2 casing at 5281'
- 4) Spot 25 sacks of cement plug at 6732'
- 5) Spot 25 sacks of cement plug at 4 1/2 stub 5356' 75' In and 75' out W.O.C. tag plug at 5213'
- 6) Spot 30 sacks of cement plug at 3250' 8 5/8 shoe and W.O.C. tag plug at 3096'
- 7) Spot 30 sacks of cement plug at 11 3/4 shoe 295' :
- 8) Spot 15 sacks of cement from 50' to surface and set up P. A. Marker

Approved as to plugging of the well bore.
Liability under bond is retained until
surface restoration is completed.

Post ID-2
6-19-92
PXA

14. I hereby certify that the foregoing is true and correct

Signed Raymond M. McPherson

Title Supervisor

Date 5-27-92

(This space for Federal or State office use)

Approved by David R. Glass

Title _____

Date 6-9-92

Conditions of approval, if any: