

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN DUPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT--" for such proposals.)

5. LEASE DESIGNATION AND SERIAL NO.

LC-062029 - RNM047

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

GOVERNMENT AM *Com*

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

TURKEY TRACK MORROW

11. SEC. T., R., M., OR BLK AND
SURVEY OR AREA

SEC 33 T18S R29E

12. COUNTY OR PARISH

EDDY

13. STATE

NM

14. PERMIT NO.

420152350800S01

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3426

16.

Check Appropriate Box To Indicate Nature of Notices, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

BHP BUILDUP & RECOMPLETE

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and five pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

TD - 11356' PBTD - 11215' PERFS - 11106' - 11172'

1. SET BLANKING PLUG IN ON/OFF TOOL @ 10999'. ROTATE OFF OF PKR & SPOT 50' OF SAND ON TOP OF PKR.
2. PU 5-1/2" RTTS & TIH. SET RTTS @ 10550'. TEST ANNULUS TO 3000#. RU HALLIBURTON AND SQUEEZE ATOKA PERFS (10675-10680') W/ 50SX LOW FLUID LOSS CMT. REVERSE OUT EXCESS CMT. WOC.
3. POOH. PU 4-5/8" BIT & 6 - 3-1/2" DC'S & TIH. DO CMT SQZ & TEST TO 3000#. POOH & LD BHA.
4. PU ON/OFF TOOL & TIH. CIRC SAND OFF PKR, RE-CONNECT TO PKR & TEST ANNULUS TO 3000#. SWAB FL.
5. RU WL, EQUALIZE PRESSURE ACROSS BLK PLG AND PULL PLG. RD WL.
6. RU HALLIBURTON AND FRAC WELL PER HALLIBURTON RECOMMENDATION (IF BHP BUILD-UP INDICATES SKIN DAMAGE).

(IF BHP BUILD-UP DOES NOT INDICATE DAMAGE: OMIT STEP #6.)

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

REGULATORY ANALYST

DATE

10/06/93

(This space for Federal or State office use)

APPROVED BY (OPIC, SGD.) JOE G. LARA

TITLE

PETROLEUM ENGINEER

DATE

10/15/93

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side