

# Geol. Tcps per Bld

|            |      |       |
|------------|------|-------|
| Gates      | 450  | (ess) |
| TRivers    | 648  | (ess) |
| Bowers     | 1014 |       |
| Queen      | 1253 |       |
| Gradyburg  | -    |       |
| San Andres | 2082 |       |
| Glorieta   | 3520 |       |
| Tubb       | 4526 |       |
| Abo        | 6030 | (c-p) |

4-30-81

Prolog

5750-6320

CDL-CNL

978-6313

MSL

Surf-6306

DLL-MLL

4316-6313



Submit 3 Copies To Appropriate District Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

CISF  
Form C-103  
Revised March 25, 1999

WELL API NO.  
30-015-23547

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name:  
Empire Abo Unit

8. Well No. J-241

9. Pool name or Wildcat Abo

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-102) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

B-P America Production Co.

3. Address of Operator

P.O. Box 1089 Eunice, N.M. 88231

4. Well Location

Unit Letter H : 1950 feet from the North line and 660 feet from the East line

Section 6 Township 18S Range 28E NMPM Eddy County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)  
KB = 13.4'

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ☐

CASING TEST AND CEMENT JOB ☐ ABANDONMENT

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

T.D. 6325', PBTD 6257', OH-6386'. OH-6276', Drain hole completion, 7"-23# csg.  
PROCEDURE TO P&A WELL:

- (1) Check tbg. press. & kill well w/brine water if necessary.
- (2) MIRU & ND well head & NU BOP & Enviro-vat.
- (3) Release TAC & POH w/ 2 3/8 tbg., TAC, SN, & Mud Anchor.
- (4) RIH w/wireline & 7" CIBP & set @ 6178'. POH w/WL.
- (5) RIH w/OET to 6178'. Tag CIBP & circ. hole w/9.5# salt gel mud.
- (6) Cap CIBP @ 6178' w/25 sxs. cmt.
- (7) PUH w/tbg. & spot 30 sxs. cmt @ 3640' to 3540'. Glorieta plug.
- (8) PUH w/tbg. & spot 30 sx. cmt plug @ 1030' to 930'. WOC & Tag. Shoe plug.
- (9) PUH w/tbg. & spot 30 sx. cmt. plug @ 465' to 365'. Yates plug.
- (10) PUH w/tbg. & spot 10 sx. cmt. plug @ 60' to surface.
- (11) Cut off well head & anchors 3' BGL. Clean up location & set dry hole marker.

Notify OCD 24 hrs. prior to any work done

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kellie H. Murrish TITLE Asst. Admin. Asst. DATE 12.18.02

Type or print name Kellie H. Murrish Telephone No. 505.394.1600

APPROVED BY [Signature] TITLE Field Rep DATE DEC 31 2002

Conditions of approval, if any

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
Revised March 25, 1999

WELL API NO.  
30-015-23547

5. Indicate Type of Lease  
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name:  
Empire Abo Unit

8. Well No. J-241

9. Pool name or Wildcat Abo

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH  
PROPOSALS.)

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

B-P America Production Co.

3. Address of Operator

P.O. Box 1089 Eunice, N.M. 88231

4. Well Location

Unit Letter H: 1950 feet from the North line and 660 feet from the East line

Section 6 Township 18S Range 28E NMPM Eddy County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)  
KB = 13.4'

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE  
COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND  
ABANDONMENT ☐

CASING TEST AND  
CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of  
starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or  
recompilation.

T.D. 6325', PBTD 6257', OH-6386'. OH-6276', Drain hole completion, 7"-23# csg.  
PROCEDURE TO P&A WELL:

- (1) Check tbg. press. & kill well w/brine water if necessary.
- (2) MIRU & ND well head & NU BOP & Enviro-vat.
- (3) Release TAC & POH w/ 2 3/8 tbg., TAC, SN, & Mud Anchor.
- (4) RIH w/wireline & 7" CIBP & set @ 6178'. POH w/WL.
- (5) RIH w/OET to 6178'. Tag CIBP & circ. hole w/9.5# salt gel mud.
- (6) Cap CIBP @ 6178' w/25 sxs. cmt.
- (7) PUH w/tbg. & spot 30 sxs. cmt @ 3640' to 3540'. Glorieta plug.
- (8) PUH w/tbg. & spot 30 sx. cmt plug @ 1030' to 930'. WOC & Tag. Shoe plug.
- (9) PUH w/tbg. & spot 30 sx. cmt. plug @ 465' to 365'. Yates plug.
- (10) PUH w/tbg. & spot 10 sx. cmt. plug @ 60' to surface.
- (11) Cut off well head & anchors 3' BGL. Clean up location & set dry hole marker.

Notify OCD 24 hrs prior to any work done

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kellie H. Murrish TITLE Sr. Admin Asst DATE 12.18.02

Type or print name Kellie H. Murrish Telephone No. 505.394.1600

(This space for State use)  
APPROVED BY [Signature] TITLE Field Rep DATE DEC 31 2002

Conditions of approval, if any