

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

YATES PETROLEUM CORPORATION

(505) 748-1471

3. Address and Telephone No.

105 South 4th St., Artesia, NM 88210

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1980' FNL & 660' FWL of Section 9-T18S-R25E, (Unit E, SWNW)

5. Lease Designation and Serial No.

NM-0487738

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Federal AB #7

9. API Well No.

30-015-23646

10. Field and Pool, or Exploratory Area

Undesignated Strawn

11. County or Parish, State

Eddy Co., NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

CONTINUED FROM PREVIOUS PAGE:

8-30-96 - Finished POOH with casing. Rigged down casing equipment. Nippled up wellhead and BOP. TIH with tubing to 3710'. Mixed and pumped 50 sacks Class C 2% CaCl₂ cement from 3710-3610'. POOH with tubing to 1000'. WOC 4 hours. TIH with tubing and tagged top of cement at 3567'. POOH with tubing to 2156'. Mixed and pumped 50 sacks Class C cement from 2156-2056'. POOH with tubing to 1226'. Mixed and pumped 10 sacks Class C 2% CaCl₂ cement from 1226-1126' (in 8-5/8" casing). POOH with tubing to 500'. WOC 3-1/2 hours. TIH with tubing and tagged top of cement at 1105'. POOH with tubing to 445'. Mixed and pumped 50 sacks Class C cement from 445-345' (in 8-5/8" casing). POOH with tubing to 40'. Mixed and pumped 10 sacks Class C cement from 40' to surface. POOH with tubing. Nippled down BOP. Cleaned location and installed regulation abandonment marker. PLUGGED AND ABANDONED - FINAL REPORT. Plugging completed 8-29-96. NOTE: Don Early w/BLM-Carlsbad witnessed cement plugging and tagging.

14. I hereby certify that the foregoing is true and correct

Signed

Rusty Klein

Title Operations Technician

Date Aug. 30, 1996

(This space for Federal or State office use)

Approved by

[Signature]

Title

Date

09/12/96

Conditions of approval, if any: