Form C-103 Revised 1-1-89	_
V	

State of New Mexico Submit 3 Copies En. , y, Minerals and Natural Resources Departmen. to Appropriate District Office OIL CONSERVATION DIVISION DISTRICT I P.O. Box 1980, Hobbs, NM 88240 WELL API NO. Santa Fe, New Mexico 87504-2088 DISTRICT II 5. Indicate Type of Lease P.O. Drawer DD, Artesia, NM 88210 FEE STATE '90s. State Oil & Gas Lease No. 1000 Rio Brazos Rd., Aztec, NM 87410 E-7179 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: West Artesia Grayburg Unit Tr 5 OAS WELL WELL X OTHER 8. Well No. 2. Name of Operator 23 Marbob Energy Corporation √ 9. Pool name or Wildcat 3. Address of Operator Artesia Queen Grbg SA P. O. Drawer 217, Artesia, NM 4. Well Location Line and 971 West Line : 2269 Feet From The South Feet From The Unit Letter __L_ **NMPM** Eddu County 185 28E Range Township 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3625.6' GR Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: ALTERING CASING REMEDIAL WORK PLUG AND ABANDON PERFORM REMEDIAL WORK PLUG AND ABANDONMENT COMMENCE DRILLING OPNS. **CHANGE PLANS** TEMPORARILY ABANDON CASING TEST AND CEMENT JOB **PULL OR ALTER CASING** OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Propose to plug and abandon as follows: Set cmt plug @ 2240-1650', tag plug @ 1650', set 25 sx plug @ 1450', set 25 sx plug @ 550, set 15 sx plug @ surface. Install dry hole marker and clean location. e to the best of my km

I hereby ogrti DATE 10/4/90 TILE Production Clerk SIGNATURE TELEPHONE NO.748 Rhonda Nelson TYPE OR PRINT NAME (This space for State Use) CONDITIONS OF APPROVAL, IF ANY: