

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

OIL CONSERVATION DIVISION

**DISTRICT I**  
P. O. Box 1980 Hobbs, NM 88240

P. O. Box 2088  
Santa Fe, New Mexico 87504-2088

**DISTRICT II**  
P. O. Drawer DD, Artesia, NM 88210

**DISTRICT III**  
1000 Rio Brazos Rd, Aztec, NM 87410

Well API NO.	30-015-23859
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B-11594-2
7. Lease Name or Unit Agreement Name	TRAVIS DEEP OHIO COM.
8. Well No.	# 1
9. Pool name or Wildcat	EMPIRE MORROW, SOUTH

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well OIL <input type="checkbox"/> GAS <input checked="" type="checkbox"/> WELL WELL OTHER	2. Name of Operator Harvey E. Yates Company
3. Address of Operator P.O. Box 1933, Roswell, NM 88202 1-505-623-6601	4. Well Location Unit Letter <u>M</u> : <u>760</u> Feet From The <u>SOUTH</u> Line and <u>660</u> Feet From The <u>WEST</u> Line Section <u>13</u> Township <u>18S</u> Range <u>28E</u> NMPM <u>EDDY</u> County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3539.1' GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER: <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.) SEE RULE 1103

3-14-2000 PLUGGER NOTIFIED OCD OF MI.  
3-15-2000 CIRC HOLE FROM 8509' w/ 10# MUD TO SURFACE.  
SPOT 25 SKS PLUG FROM 8509' TO 8159'.  
TEST CSG. DID NOT HOLD. PERF @ 6259'. RIH w/ PKR TO 5840'. ESTABLISH INJ RATE & SHUT IN.  
3-16-2000 SQZ 35 SKS TO 6150'. WOC. POOH w/ PKR. GIH w/ WIRELINE & TAG CMT @ 6088'.  
3-17-2000 CUT BUT UNABLE TO PULL CSG @ 3202'. CUT CSG @ 3100'. LD CSG. SI.  
3-20-2000 RIH w/ TBG TO 3265'. CIRC 10# MUD. SPOT 50 SKS @ 3265'. WOC. TAG @ 3094'. RE-SET PLUG w/  
50 SKS @ 3094'. POOH.  
3-21-2000 TAG PLUG @ 2895'. SPOT 35 SKS FROM 408-273'. SPOT 10 SK PLUG SURFACE PLUG @ 30'.  
CUT OFF WH & INSTALL DRY HOLE MARKER.  
CUT OFF ANCHORS, BACKFILL WORK PIT & CLEAN LOCATION. P&A COMPLETE.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ray F. Nokes TITLE PROD. MGR. / ENGINEER. Date 3/29/00  
TYPE OR PRINT NAME RAY F. NOKES TELEPHONE NO. 1-505-623-6601

(This space for State use)

Approved by [Signature] Title Field Rep I Date 5-23-00  
Conditions of approval, if any: