

L CONSERVATION DIVISIC

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

RECEIVED

AUG 17 1982

Form C-103

Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.O.S.	
LAND OFFICE	
OPERATOR	1

5a. Indicate Type of Lease State ☐ Fee ☒
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name Kelly
9. Well No. 2
10. Field and Pool, or Wildcat Und. Atoka Yeso
12. County Eddy

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - I" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒	GAS WELL ☐	OTHER ☐
Name of Operator Ralph Nix		
Address of Operator P. O. Box 617 Artesia, New Mexico 88210		
Location of Well UNIT LETTER <u>K</u> <u>1650</u> FEET FROM THE <u>South</u> LINE AND <u>2310</u> FEET FROM THE <u>West</u> LINE, SECTION <u>27</u> TOWNSHIP <u>18S</u> RANGE <u>26E</u> NMPH.		

15. Elevation (Show whether DF, RT, GR, etc.)

3345' GL

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
NULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	OTHER <u>Stimulation & Perforation</u> ☒
		Plug Back	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7/20/82 RU Dresser Atlas RIH w/Wireline conveyed cast iron bridge plug & set @ 3735' KB. RIH w/dump bailer & cap bridge plug w/3 sx cement for 40' total in 4 1/2 over plug. RIH w/ JJKS and perforate 6 holes, 1 shot per interval @ 3590', 92, 94, 96, 98, 3600, size of holes 0.37" & secure well head.

7/23/82 RU Well Units @ 9:30 am. RIH w/Baker AD-1 packer, SN, 115 jts 2 3/8" tubing to 3631.62' gl, circulate hole w/2% KCL spot 1 bbls acid, pull up 3 jts to 3535.35' GL, stimulate w/2000 gals 15% acid, Max PSI 3400, Ave PSI 2200, Ave rate 4 BPM, Total acid 47.6, total fluid 62.3, ISIP 900 PSI, 5 min 750 PSI, 10 min 700, 15 min 600 PSI. Drop 2 balls every 7 bbls, ball out on 6th ball, surged off, finish out very weak flow to pit, left open 45 min. RU & swab acid back release packer, lower tubing 3 jts running packer over perfs, run rods 3/4" & 7/8" all Norris type 90, 10' insert traveling barrell pump bottom of 2 3/8" tubing 3631.62' GL. Packer hanging loose in hole. Rods stacked out, hang on CMC 114 pump jack, set to pumping.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

WED Ralph Nix, Jr. TITLE Ralph Nix, Jr. DATE 8/10/82

APPROVED BY Leslie J. Clements TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: