

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ well gas ☐ well other ☐
2. NAME OF OPERATOR
Premier Production Co. ✓
3. ADDRESS OF OPERATOR
324 W. Main, Artesia, NM 88210
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 990' FSL 330' FWL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	<input type="checkbox"/>		<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>		<input type="checkbox"/>
SHOOT OR ACIDIZE	<input checked="" type="checkbox"/>		<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>		<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>		<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>		<input type="checkbox"/>
CHANGE ZONES	<input type="checkbox"/>		<input type="checkbox"/>
ABANDON*	<input type="checkbox"/>		<input type="checkbox"/>
(other)			

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

3-29-83 Rig up & perf as follows: 1st stage: 3489', 90, 91, 92, 93, 94, 95, 96, 97, 98, 10-42" holes; 2nd stage: 3398', 99, 3400, 01, 02, 03, 04, 05, 06, 07, 10shots & 3254', 55, 56, 57, 58, 59, 6 shots. Acidize perfs 3489-98' w/750gals 20% NEFE; swabbed load+ (all water). 3/30 acidize perfs 3398-3407' w/1000gals 20% NEFE acid, swabbed load+ (all water). Acidize perfs 3254-59' w/500gals 20% NEFE, swabbed load+(all water) 3/31 rig up & perf as follows 3134', 35, 36, 40, 41, 57, 58, 59, 60, 61 & 62; 11 holes; 3056', 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 12 holes; 2951', 52, 53, 54, 55, 56, 57, 58, 59, 60, 10 holes. 4/1 Rig up & acidize perfs 3134-62' w/800gals 15% NE; swab load+; trace of oil, 99% water. 4/1 acidize perfs 3056-68' w/1000gal 15% NE; swabbed dry, recovered 30-40% oil. Frac w/40,000gals 2% KCL, 36,000# 20-40, 11,700# 10-20 sand. Put on pump to test.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE [Signature] DATE 4/25/83

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

5. LEASE NM 17223
6. IF INDIAN, ALLOTTEE OR TRIBE NAME ?
7. UNIT AGREEMENT NAME RECEIVED
8. FARM OR LEASE NAME Alice Federal
9. WELL NO. 1
10. FIELD OR WILDCAT NAME <i>Acidize 9-6</i> Undesignated San Andres
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 23 T-18S, R-29E
12. COUNTY OR PARISH Eddy
13. STATE NM
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD) GL 3473'

(NOTE: Report results of multiple completion or zone change on Form 9-330.)