

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

JUN 10 1991

O. C. D.

WELL API NO. 30-015-24403
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Whirlwind WL
8. Well No. 1
9. Pool name or Wildcat Undes. Canyon
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3533' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER RECOMPLETION
2. Name of Operator YATES PETROLEUM CORPORATION
3. Address of Operator 105 South 4th St., Artesia, NM 88210
4. Well Location Unit Letter M : 660 Feet From The South Line and 660 Feet From The West Line Section 15 Township 18S Range 25E NMPM Eddy County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-25-91. Set CIBP at 8175', capped with 35' cement. Perforated 7943-46' and 7896-7902' w/22 - .40" holes (2 SPF). TIH w/RBP and packer. Straddle perfs 7943-7902'. Acidize w/ 2500 gals 15% NEFE acid. Swabbed with show of gas.

4-27-91. Bled down and swabbed - had continuous blow of gas. Well flowed 70 psi on 1/8" choke = 29 mcfd.

4-28-30-91. FTP 15# on 1/4" choke = 42 mcfd. Release packer. Retrieve RBP, set at 7860'. Tested to 2000 psi, OK. TOH with tubing and packer. Perforated 7768-90', 7657-64' and 7630-40' w/37 - .40" holes (1 SPF). Straddled perfs 7768-90' with RBP and packer. Acidized w/4500 gals 15% NEFE acid. Moved tools and straddled perfs 7630-7664'. Acidized w/4200 gals 15% NEFE acid. Straddled perfs 7630-7946'. RU swab and swabbed back. Swabbed and tested 5-1-91 - 5-27-91.

6-4-91. RUPU. Pulled tubing and packer. Perforated 7362-7382' w/20 .40" holes (2 SPF): 7362, 64, 66, 68, 72, 74, 76, 77, 80, and 7382'. RIH w/RBP and packer, set RBP, tested to 2500 psi. Straddled perfs 7362-7382', acidized w/2000 gals 15% acid.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 6-7-91
TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY
MIKE WILLIAMS
SUPERVISOR, DISTRICT II

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

JUN 18 1991