

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-015-24403
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> GAS Well <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Lease Name or Unit Agreement Name Whirlwind WL
2. Name of Operator YATES PETROLEUM CORPORATION	
3. Address of Operator 105 South Fourth Street - Artesia, NM 88210	8. Well No. 1
4. Well Location Unit Letter M : 660 Feet From The South Line and 660 Feet From The West Line Section 15 Township 18S Range 25E NMPM Eddy County	9. Pool name or Wildcat Undesignated Eddy Group 1
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3533' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-3-96 - Moved in and rigged up pulling unit. Nippled down pumping unit. POOH with rods. Cut off wellhead bolts. Nippled down wellhead and nippled up BOP. POOH with tubing, seating nipple, perforated sub and mud anchor. Rigged up wireline. TIH with 4-1/2" CIBP and set at 2150'. Rigged down wireline. TIH with 2-3/8" tubing and tagged CIBP. Shut down for night.

2-6-96 - Spot 35 bbls plug mud from 2150' to surface. Mixed and pumped 5 sacks Class C cement from 2150-2030' (in 4-1/2" casing). POOH with tubing. Rigged up wireline. TIH with perforating gun and perforated 4 holes at 1220'. Rigged down wireline. TIH with 4-1/2" cement retainer and set retainer at 1120'. Mixed and pumped 100 sacks Class C cement as follows: pumped 70 sacks thru cement retainer down 4-1/2" casing and out at perforations. Pulled out of cement retainer and dumped 30 sacks on top of cement retainer. Estimate top of cement at 720'±. POOH with 2-3/8" tubing. Rigged up wireline. TIH with perforating gun and perforated 4 holes at 430'. Rigged down wireline. TIH with cement retainer and set retainer at 335'. Mixed and pumped 35 sacks Class C cement as follows: 25 sacks thru cement retainer down 4-1/2" casing and out at perforations. Pulled out of

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

CONTINUED ON NEXT PAGE:

SIGNATURE Rusty Klein TITLE Production Clerk DATE 2-19-96
TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505-748-1471

(This space for State Use)

APPROVED BY Mike S. Galloway TITLE Field Rep. I DATE 4-29-96