NM OIL COMS. CO ISSION

Drawer DD UNITED STATES

Artesia, MM 88610

FORM APPROVED

c191

Budget Bureau No. 1004-0135 Expires: March 31, 1993

(June 1990) DEPARTMENT OF THE INTERIOR

Form 3160-5

BUREAU OF LAND MANAGEMENT		5. Lease Designation and Serial No.
SUNDRY NOTICES AND REPORTS ON WELLS		NM 15007
Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  Use "APPLICATION FOR PERMIT—" for such proposals		6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation
1. Type of Well	e m = 0 ·	
Well Gas Well Other FFB 2 ~ 1993		8. Well Name and No.  Bear Draw
FROSTMAN OIL COMPAN	0, c. d.	9. API Well No.
3. Address and Telephone No.		5
		10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		Bear Draw Q. GR. SA
Sec. 21 T-16-S R-29-E $(60/S)$ 2310/F		11. County or Parish, State
660/5 2310/	E W'	EDDY N.M.
12. CHECK APPROPRIATE BOX	(s) TO INDICATE NATURE OF NOTICE, REPOR	RT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent	X Abandonment	Change of Plans
_	Recompletion	New Construction
Subsequent Report	Plugging Back	Non-Routine Fracturing
	Casing Repair	Water Shut-Off
Einal Abandonment Notice	Altering Casing	Conversion to Injection
	Other	Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
13. Describe Proposed or Completed Operations (Clearly state a	all pertinent details, and give pertinent dates, including estimated date of starting	any proposed work. If well is directionally drilled.
	cal depths for all markers and zones pertinent to this work.)*	Post ID-2
(1) Set $4\frac{1}{2}$ CIBP @ 1800' and cap w/35' cement on top.		2-26-93
(2) Load hole w/mud		
(3) Spot 25 sacks cement plug @ 1150' W.O.C. tag @ 961 (4) Perforate @ 325'		PXA
-	lid not get circulation to surface. W.O	) C
Tagged plug @ 227'	ita not get circulation to surface. w.c	
(6) Perforated 4½ casing @200	)	88 =
(7) Pumped 65 sack cement did Tagged plug at 223'	not get circulation to surface W.O.C.	
(8) Cut & pull 4½ casing @ 20	001	177 
	200 to surface. Set P.A. marker	rre
-		3 2
	Approved as to progging	
	Liability under bond is a softest castoration is co	6thined until
4. I hereby certify that the foregoing is true and correct		
Signed Mayoner Ma derad	Title Maribourse	Date 1-13-93
		Date
(This space for Federal or State office use)  Approved by (DLIG, SOD) DAND R. GLASS  Title PETROLEUM ENGINEER		
Conditions of approval, if any:		Date