Form 3160-5 June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993 5. Lease Designation and Serial No.

Artesia, NM 88210

Drawer DD

CHURDY HATIAT		NM-34452
	ES AND REPORTS ON WELLS	6. If Indian, Allottee or Tribe Name
o not use this form for proposals to	drill or to deepen or reentry to a different reservoi	r.
Use "APPLICATION !	FOR PERMIT—" for such proposals RECEIVED	
		7. If Unit or CA, Agreement Designation
SUBA	MIT IN TRIPLICATE	77 27 27 27 27 27 27 27 27 27 27 27 27 2
ype of Well	JUN 30 '94	
Oil Gas Other		8. Well Name and No.
ame of Operator	C. C. D.	Northwestern Shores XR F
YATES PETROLEUM CORPORATIO	N (505) 748-14₹€\$IA. OFFICE	9. API Well No. Com #1
Address and Telephone No.		30-015-24600
105 South 4th St., Artesia	. NM 88210	10. Field and Pool, or Exploratory Area
ocation of Well (Footage, Sec., T., R., M., or Surve		Undesignated Abo
	ction 36-T18S-R26E (Unit B, NWNE)	11. County or Parish, State
100 FML & 1300 FEL OI Sec	CION 30-1103-R20E (ONIC D, NWNE)	
		Ell C NV
·		Eddy Co., NM
CHECK APPROPRIATE BO	OX(s) TO INDICATE NATURE OF NOTICE, REF	PORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent	Abandonment	Change of Plans
Notice of Intent	Recompletion	New Construction
∇ a	X Plugging Back	Non-Routine Fracturing
X Subsequent Report	Casing Repair	Water Shut-Off
	, <u> </u>	Conversion to Injection
Final Abandonment Notice	☐ Altering Casing	r ·
	Other	Dispose Water (Note: Report results of multiple completion on Well
		Completion or Recompletion Report and Log form.)
Describe Proposed or Completed Operations (Clearly s	state all pertinent details, and give pertinent dates, including estimated date of sta	arting any proposed work. If well is directionally drilled,
managed and analysis and analysis and a second a second and a second a	the state of the s	• • • •
give subsurface locations and measured and true	vertical depths for all markers and zones pertinent to this work.)*	
give subsurface locations and measured and true	vertical depths for all markers and zones pertinent to this work.)*	•
give subsurface locations and measured and true -24-94 - Moved in and rigge	vertical depths for all markers and zones pertinent to this work.)* ed up pulling unit. Bled well down. I	Loaded tubing with 55 bbls
give subsurface locations and measured and true -24-94 - Moved in and rigge CL. Loaded casing with 80	vertical depths for all markers and zones pertinent to this work.) ed up pulling unit. Bled well down. I bbls. Tested annulus to 1000 psi. Re	Loaded tubing with 55 bbls eleased packer. Strip on
give subsurface locations and measured and true -24-94 - Moved in and rigge CL. Loaded casing with 80 OP. Ran 3 joints of tubing	vertical depths for all markers and zones pertinent to this work.) ed up pulling unit. Bled well down. I bbls. Tested annulus to 1000 psi. Re g. Tagged at 9344'. TOOH with packer.	Loaded tubing with 55 bbls eleased packer. Strip on Shut in.
give subsurface locations and measured and true -24-94 - Moved in and rigge CL. Loaded casing with 80 OP. Ran 3 joints of tubing -25-94 - Rigged up Schlumbe	vertical depths for all markers and zones pertinent to this work.) ed up pulling unit. Bled well down. I bbls. Tested annulus to 1000 psi. Re g. Tagged at 9344'. TOOH with packer. erger. Set 5-1/2" CIBP at 9200'. Capp	Loaded tubing with 55 bbls eleased packer. Strip on Shut in.
give subsurface locations and measured and true -24-94 - Moved in and rigge CL. Loaded casing with 80 OP. Ran 3 joints of tubing -25-94 - Rigged up Schlumbe erforated 4 holes at 6430'.	vertical depths for all markers and zones pertinent to this work.) ed up pulling unit. Bled well down. I bbls. Tested annulus to 1000 psi. Re g. Tagged at 9344'. TOOH with packer. erger. Set 5-1/2" CIBP at 9200'. Capp . TIH w/packer. Laid down 3000' of to	Loaded tubing with 55 bbls eleased packer. Strip on Shut in. Ded with 35' of cement.
give subsurface locations and measured and true -24-94 - Moved in and rigge CL. Loaded casing with 80 OP. Ran 3 joints of tubing -25-94 - Rigged up Schlumbe erforated 4 holes at 6430'. ressured down tubing to 200	vertical depths for all markers and zones pertinent to this work.) ed up pulling unit. Bled well down. I bbls. Tested annulus to 1000 psi. Reg. Tagged at 9344'. TOOH with packer. erger. Set 5-1/2" CIBP at 9200'. Capp. TIH w/packer. Laid down 3000' of tu 00 psi. Broke circulation up 9-5/8" X	Loaded tubing with 55 bbls eleased_packer. Strip on Shut in. Ded with 35' of cement. Ibing. Set packer at 6380'. 5-1/2" annulus. Pumped
give subsurface locations and measured and true -24-94 - Moved in and rigge CL. Loaded casing with 80 OP. Ran 3 joints of tubing -25-94 - Rigged up Schlumbe erforated 4 holes at 6430'. ressured down tubing to 200 0 bbls at 4 BPM at 1000 psi	vertical depths for all markers and zones pertinent to this work.) ed up pulling unit. Bled well down. I bbls. Tested annulus to 1000 psi. Reg. Tagged at 9344'. TOOH with packer. erger. Set 5-1/2" CIBP at 9200'. Capp. TIH w/packer. Laid down 3000' of to 00 psi. Broke circulation up 9-5/8" X i. Released packer. TOOH. Set 5-1/2'	Loaded tubing with 55 bbls eleased packer. Strip on Shut in. Ded with 35' of cement. Libing. Set packer at 6380'. 5-1/2" annulus. Pumped cement retainer at 6380'.
give subsurface locations and measured and true -24-94 - Moved in and rigge CL. Loaded casing with 80 OP. Ran 3 joints of tubing -25-94 - Rigged up Schlumbe erforated 4 holes at 6430'. ressured down tubing to 200 0 bbls at 4 BPM at 1000 psi	vertical depths for all markers and zones pertinent to this work.) ed up pulling unit. Bled well down. I bbls. Tested annulus to 1000 psi. Reg. Tagged at 9344'. TOOH with packer. erger. Set 5-1/2" CIBP at 9200'. Capp. TIH w/packer. Laid down 3000' of tu 00 psi. Broke circulation up 9-5/8" X	Loaded tubing with 55 bbls eleased packer. Strip on Shut in. Ded with 35' of cement. Libing. Set packer at 6380'. 5-1/2" annulus. Pumped cement retainer at 6380'.
give subsurface locations and measured and true -24-94 - Moved in and rigge CL. Loaded casing with 80 OP. Ran 3 joints of tubing -25-94 - Rigged up Schlumbe erforated 4 holes at 6430'. ressured down tubing to 200 0 bbls at 4 BPM at 1000 psi	vertical depths for all markers and zones pertinent to this work.) ed up pulling unit. Bled well down. I bbls. Tested annulus to 1000 psi. Reg. Tagged at 9344'. TOOH with packer. erger. Set 5-1/2" CIBP at 9200'. Capp. TIH w/packer. Laid down 3000' of to 00 psi. Broke circulation up 9-5/8" X i. Released packer. TOOH. Set 5-1/2'	Loaded tubing with 55 bbls eleased packer. Strip on Shut in. Ded with 35' of cement. Libing. Set packer at 6380'. 5-1/2" annulus. Pumped cement retainer at 6380'.
give subsurface locations and measured and true -24-94 - Moved in and rigge CL. Loaded casing with 80 OP. Ran 3 joints of tubing -25-94 - Rigged up Schlumbe erforated 4 holes at 6430'. ressured down tubing to 200 0 bbls at 4 BPM at 1000 psi	vertical depths for all markers and zones pertinent to this work.) ed up pulling unit. Bled well down. I bbls. Tested annulus to 1000 psi. Reg. Tagged at 9344'. TOOH with packer. erger. Set 5-1/2" CIBP at 9200'. Capp. TIH w/packer. Laid down 3000' of to 00 psi. Broke circulation up 9-5/8" X i. Released packer. TOOH. Set 5-1/2'	Loaded tubing with 55 bbls eleased packer. Strip on Shut in. Ded with 35' of cement. Libing. Set packer at 6380'. 5-1/2" annulus. Pumped cement retainer at 6380'.
give subsurface locations and measured and true -24-94 - Moved in and rigge CL. Loaded casing with 80 OP. Ran 3 joints of tubing -25-94 - Rigged up Schlumbe erforated 4 holes at 6430'. ressured down tubing to 200 0 bbls at 4 BPM at 1000 psi	vertical depths for all markers and zones pertinent to this work.) ed up pulling unit. Bled well down. I bbls. Tested annulus to 1000 psi. Reg. Tagged at 9344'. TOOH with packer. erger. Set 5-1/2" CIBP at 9200'. Capp. TIH w/packer. Laid down 3000' of to 00 psi. Broke circulation up 9-5/8" X i. Released packer. TOOH. Set 5-1/2'	Loaded tubing with 55 bbls eleased packer. Strip on Shut in. Ded with 35' of cement. Libing. Set packer at 6380'. 5-1/2" annulus. Pumped cement retainer at 6380'.
give subsurface locations and measured and true -24-94 - Moved in and rigge CL. Loaded casing with 80 OP. Ran 3 joints of tubing -25-94 - Rigged up Schlumbe erforated 4 holes at 6430'. ressured down tubing to 200 0 bbls at 4 BPM at 1000 psi	vertical depths for all markers and zones pertinent to this work.) ed up pulling unit. Bled well down. I bbls. Tested annulus to 1000 psi. Reg. Tagged at 9344'. TOOH with packer. erger. Set 5-1/2" CIBP at 9200'. Capp. TIH w/packer. Laid down 3000' of to 00 psi. Broke circulation up 9-5/8" X i. Released packer. TOOH. Set 5-1/2'	Loaded tubing with 55 bbls eleased packer. Strip on Shut in. Ded with 35' of cement. Libing. Set packer at 6380'. 5-1/2" annulus. Pumped cement retainer at 6380'.
give subsurface locations and measured and true -24-94 - Moved in and rigge CL. Loaded casing with 80 OP. Ran 3 joints of tubing -25-94 - Rigged up Schlumbe erforated 4 holes at 6430'. ressured down tubing to 200 O bbls at 4 BPM at 1000 psi	vertical depths for all markers and zones pertinent to this work.) ed up pulling unit. Bled well down. I bbls. Tested annulus to 1000 psi. Reg. Tagged at 9344'. TOOH with packer. erger. Set 5-1/2" CIBP at 9200'. Capp. TIH w/packer. Laid down 3000' of to 00 psi. Broke circulation up 9-5/8" X i. Released packer. TOOH. Set 5-1/2'	Loaded tubing with 55 bbls eleased packer. Strip on Shut in. Ded with 35' of cement. Libing. Set packer at 6380'. 5-1/2" annulus. Pumped cement retainer at 6380'.
give subsurface locations and measured and true -24-94 - Moved in and rigge CL. Loaded casing with 80 OP. Ran 3 joints of tubing -25-94 - Rigged up Schlumbe erforated 4 holes at 6430'. ressured down tubing to 200 0 bbls at 4 BPM at 1000 psi	vertical depths for all markers and zones pertinent to this work.) ed up pulling unit. Bled well down. I bbls. Tested annulus to 1000 psi. Reg. Tagged at 9344'. TOOH with packer. erger. Set 5-1/2" CIBP at 9200'. Capp. TIH w/packer. Laid down 3000' of to 00 psi. Broke circulation up 9-5/8" X i. Released packer. TOOH. Set 5-1/2'	Loaded tubing with 55 bbls eleased packer. Strip on Shut in. Ded with 35' of cement. Libing. Set packer at 6380'. 5-1/2" annulus. Pumped cement retainer at 6380'.
give subsurface locations and measured and true -24-94 - Moved in and rigge CL. Loaded casing with 80 OP. Ran 3 joints of tubing -25-94 - Rigged up Schlumbe erforated 4 holes at 6430'. ressured down tubing to 200 0 bbls at 4 BPM at 1000 psi	vertical depths for all markers and zones pertinent to this work.) ed up pulling unit. Bled well down. I bbls. Tested annulus to 1000 psi. Reg. Tagged at 9344'. TOOH with packer. erger. Set 5-1/2" CIBP at 9200'. Capp. TIH w/packer. Laid down 3000' of to 00 psi. Broke circulation up 9-5/8" X i. Released packer. TOOH. Set 5-1/2'	Loaded tubing with 55 bbls eleased packer. Strip on Shut in. Ded with 35' of cement. Libing. Set packer at 6380'. 5-1/2" annulus. Pumped cement retainer at 6380'.
give subsurface locations and measured and true -24-94 - Moved in and rigge CL. Loaded casing with 80 OP. Ran 3 joints of tubing -25-94 - Rigged up Schlumbe erforated 4 holes at 6430'. ressured down tubing to 200 0 bbls at 4 BPM at 1000 psi	vertical depths for all markers and zones pertinent to this work.) ed up pulling unit. Bled well down. I bbls. Tested annulus to 1000 psi. Reg. Tagged at 9344'. TOOH with packer. erger. Set 5-1/2" CIBP at 9200'. Capp. TIH w/packer. Laid down 3000' of to 00 psi. Broke circulation up 9-5/8" X i. Released packer. TOOH. Set 5-1/2'	Loaded tubing with 55 bbls eleased packer. Strip on Shut in. Ded with 35' of cement. Libing. Set packer at 6380'. 5-1/2" annulus. Pumped cement retainer at 6380'.
give subsurface locations and measured and true -24-94 - Moved in and rigge CL. Loaded casing with 80 OP. Ran 3 joints of tubing -25-94 - Rigged up Schlumbe erforated 4 holes at 6430'. ressured down tubing to 200 0 bbls at 4 BPM at 1000 psi	vertical depths for all markers and zones pertinent to this work.) ed up pulling unit. Bled well down. I bbls. Tested annulus to 1000 psi. Reg. Tagged at 9344'. TOOH with packer. erger. Set 5-1/2" CIBP at 9200'. Capp. TIH w/packer. Laid down 3000' of to 00 psi. Broke circulation up 9-5/8" X i. Released packer. TOOH. Set 5-1/2'	Loaded tubing with 55 bbls eleased packer. Strip on Shut in. Ded with 35' of cement. Libing. Set packer at 6380'. 5-1/2" annulus. Pumped cement retainer at 6380'.
give subsurface locations and measured and true -24-94 - Moved in and rigge CL. Loaded casing with 80 OP. Ran 3 joints of tubing -25-94 - Rigged up Schlumbe erforated 4 holes at 6430'. ressured down tubing to 200 0 bbls at 4 BPM at 1000 psi	vertical depths for all markers and zones pertinent to this work.) ed up pulling unit. Bled well down. I bbls. Tested annulus to 1000 psi. Reg. Tagged at 9344'. TOOH with packer. erger. Set 5-1/2" CIBP at 9200'. Capp. TIH w/packer. Laid down 3000' of to 00 psi. Broke circulation up 9-5/8" X i. Released packer. TOOH. Set 5-1/2'	Loaded tubing with 55 bbls eleased packer. Strip on Shut in. Deed with 35' of cement. In the second
give subsurface locations and measured and true -24-94 - Moved in and rigge CL. Loaded casing with 80 OP. Ran 3 joints of tubing -25-94 - Rigged up Schlumbe erforated 4 holes at 6430'. ressured down tubing to 200 0 bbls at 4 BPM at 1000 psi IH w/stinger and tubing.	vertical depths for all markers and zones pertinent to this work.) ed up pulling unit. Bled well down. It bbls. Tested annulus to 1000 psi. Reg. Tagged at 9344'. TOOH with packers. erger. Set 5-1/2" CIBP at 9200'. Capp. TIH w/packer. Laid down 3000' of tu 000 psi. Broke circulation up 9-5/8" Xi. Released packer. TOOH. Set 5-1/2' Sting into retainer. Pumped 50 bbls the set of the se	Loaded tubing with 55 bbls eleased packer. Strip on Shut in. Deed with 35' of cement. Ibing. Set packer at 6380'. 5-1/2" annulus. Pumped cement retainer at 6380'. In ru retainer. Shut in.
give subsurface locations and measured and true -24-94 - Moved in and rigge CL. Loaded casing with 80 OP. Ran 3 joints of tubing -25-94 - Rigged up Schlumbe erforated 4 holes at 6430'. ressured down tubing to 200 0 bbls at 4 BPM at 1000 psi IH w/stinger and tubing.	vertical depths for all markers and zones pertinent to this work.) ed up pulling unit. Bled well down. It bbls. Tested annulus to 1000 psi. Reg. Tagged at 9344'. TOOH with packers. erger. Set 5-1/2" CIBP at 9200'. Capp. TIH w/packer. Laid down 3000' of tu 000 psi. Broke circulation up 9-5/8" X i. Released packer. TOOH. Set 5-1/2' Sting into retainer. Pumped 50 bbls the set of the s	Loaded tubing with 55 bbls eleased packer. Strip on Shut in. Deed with 35' of cement. Ibing. Set packer at 6380' 5-1/2" annulus. Pumped cement retainer at 6380'. In ru retainer. Shut in.
give subsurface locations and measured and true -24-94 - Moved in and rigge CL. Loaded casing with 80 OP. Ran 3 joints of tubing -25-94 - Rigged up Schlumbe erforated 4 holes at 6430'. ressured down tubing to 200 0 bbls at 4 BPM at 1000 psi	vertical depths for all markers and zones pertinent to this work.) ed up pulling unit. Bled well down. It bbls. Tested annulus to 1000 psi. Reg. Tagged at 9344'. TOOH with packers. erger. Set 5-1/2" CIBP at 9200'. Capp. TIH w/packer. Laid down 3000' of tu 000 psi. Broke circulation up 9-5/8" Xi. Released packer. TOOH. Set 5-1/2' Sting into retainer. Pumped 50 bbls the set of the se	Loaded tubing with 55 bbls eleased packer. Strip on Shut in. Deed with 35' of cement. In the second
give subsurface locations and measured and true -24-94 - Moved in and rigge CL. Loaded casing with 80 OP. Ran 3 joints of tubing -25-94 - Rigged up Schlumbe erforated 4 holes at 6430'. ressured down tubing to 200 0 bbls at 4 BPM at 1000 psi IH w/stinger and tubing.	ed up pulling unit. Bled well down. It bbls. Tested annulus to 1000 psi. Reg. Tagged at 9344'. TOOH with packer. erger. Set 5-1/2" CIBP at 9200'. Capp. TIH w/packer. Laid down 3000' of tu 00 psi. Broke circulation up 9-5/8" X i. Released packer. TOOH. Set 5-1/2' Sting into retainer. Pumped 50 bbls the set of the set o	Loaded tubing with 55 bbls eleased packer. Strip on Shut in. Ded with 35' of cement. Ibing. Set packer at 6380' 5-1/2" annulus. Pumped cement retainer at 6380'. In ru retainer. Shut in.
give subsurface locations and measured and true -24-94 - Moved in and rigge CL. Loaded casing with 80 OP. Ran 3 joints of tubing -25-94 - Rigged up Schlumbe erforated 4 holes at 6430'. ressured down tubing to 200 0 bbls at 4 BPM at 1000 psi IH w/stinger and tubing.	wertical depths for all markers and zones pertinent to this work.) ed up pulling unit. Bled well down. It bbls. Tested annulus to 1000 psi. Reg. Tagged at 9344'. TOOH with packer. erger. Set 5-1/2" CIBP at 9200'. Capp. TIH w/packer. Laid down 3000' of tu 00 psi. Broke circulation up 9-5/8" X i. Released packer. TOOH. Set 5-1/2' Sting into retainer. Pumped 50 bbls the set of the set	Loaded tubing with 55 bbls eleased packer. Strip on Shut in. Ded with 35' of cement. In the set packer at 6380's 5-1/2" annulus. Pumped cement retainer at 6380's for the set packer at 6380's
give subsurface locations and measured and true -24-94 - Moved in and rigge CL. Loaded casing with 80 OP. Ran 3 joints of tubing -25-94 - Rigged up Schlumbe erforated 4 holes at 6430'. ressured down tubing to 200 0 bbls at 4 BPM at 1000 psi IH w/stinger and tubing.	ed up pulling unit. Bled well down. It bbls. Tested annulus to 1000 psi. Reg. Tagged at 9344'. TOOH with packer. erger. Set 5-1/2" CIBP at 9200'. Capp. TIH w/packer. Laid down 3000' of tu 00 psi. Broke circulation up 9-5/8" X i. Released packer. TOOH. Set 5-1/2' Sting into retainer. Pumped 50 bbls the set of the set o	Loaded tubing with 55 bbls eleased packer. Strip on Shut in. Ded with 35' of cement. Ibing. Set packer at 6380'. 5-1/2" annulus. Pumped cement retainer at 6380'. In ru retainer. Shut in.

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.