

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.O.S.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

RECEIVED BY
DEC 08 1983
O. C. D.
ARTESIA, NM

5a. Indicate Type of Lease
State ☒ For ☐
5. State Oil & Gas Lease No.
L-321

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐
Name of Operator
Yates Petroleum Corporation ☒
Address of Operator
207 South 4th St., Artesia, NM 88210
Location of Well
UNIT LETTER 0 330 FEET FROM THE South LINE AND 2310 FEET FROM
THE East LINE, SECTION 7 TOWNSHIP 18S RANGE 25E NEARBY.

7. Unit Agreement Name
8. Farm or Lease Name
Brownwick YD State
9. Well No.
1
10. Field and Pool, or Wildcat
Undes. San Andres
11. County
Eddy

15. Elevation (Show whether DF, RT, GR, etc.)
3625' GR

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
		OTHER <u>Perforate, Treat</u> <input checked="" type="checkbox"/>	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 1870'. Moved packer to 1727'. Made 10 swab runs after perforating 1734-51' and treating well. Slight show of gas. Moved RBP to 1566'. POH to 1459' and spotted acid. TOOH w/packer. WIH and perforated 1459-1493' w/10 .42" holes as follows: 1459, 60½, 70, 76, 80, 80½, 84, 85, 92, and 93'. POH. RIH w/packer and tubing to 1355'. Pump 3000 gallons 15% DS-30 acid and 20 ball sealers. No show of oil or gas. Moved RBP to 1418'. TOOH w/packer. WIH and perforated 1161-1374' w/18 .41" holes as follows: 1161, 67, 68, 77, 1190, 1213, 14, 32, 34, 88, 92, 96, 1300, 66½, 67½, 72, 73 and 74'. Set packer at 1317'. Acidized w/1000 g. 15% DS-30 acid. Moved RBP, set at 1350'. Set packer 1265'. Acidized w/1000 g. 15% DS-30 acid. Moved packer to 1077'. Acidized w/2000 gallons 15% DS-30 acid. Moved bridge plug and packer. Swabbed well. No show of oil or gas. Prep to P&A.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

CHIEF Leslie A. Clements TITLE Production Supervisor DATE 12-7-83
Original Signed By
Leslie A. Clements
Supervisor District II
PROVED BY _____ TITLE _____ DATE DEC 13 1983
CONDITIONS OF APPROVAL, IF ANY: