

Expires August 31, 1985

4/5F

RECEIVED BY 8125AU OF LAND MANAGEMENT

SUNDY NOTICES AND REPORTS ON WELLS

Not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

O. G. D. ☒ CAS ☐ WELL ☐ OTHER

5. LEASE DESIGNATION AND SERIAL NO.
NM 36497

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Anadarko 13 Federal

9. WELL NO.
1

10. FIELD AND POOL, OR WILDCAT
Artesia Oil Pool

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 13, T-18S, R-27E

12. COUNTY OR PARISH
Eddy

13. STATE
NM

3. ADDRESS OF OPERATOR
Dickson Petroleum, Inc. (Arlen Dickson, 915-686-9559)

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)
At surface

1724' FNL & 2279' FEL of Sec 13, T-18S, R-27E. (Unit G)
(SW/4NE/4)

14. PERMIT NO.
15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3561' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
(Other) <input type="checkbox"/>	

SUBSEQUENT REPORT OF:


WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1/8/85: Verbal Approval from Bob Pitsky to plug and abandon. His instruction were to
Spot 30 sxs plug from 2050'-2150'.
Spot 35 sxs plug from 1275'-1375'.
Spot 95 sxs plug from 290'-450' with 4% CaCl Class "C".
Tag at 390'.
Spot 100 sxs from 390'-135'.
Tag plug at 135'.

50' surface plug



18. I hereby certify that the foregoing is true and correct

SIGNED Marlysa Reynolds

TITLE Consultant

DATE 1/17/85

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE 1-21-85

*See Instructions on Reverse Side