

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

SEP 24 1992

O. C. D.
ARTESIA OFFICE

WELL API NO.

30-015-25271

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE 'APPLICATION FOR PERMIT'
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☐

GAS
WELL ☐

OTHER SWD

2. Name of Operator

Phillips Petroleum Company ✓

3. Address of Operator

4001 Penbrook St., Odessa, TX 79762

4. Well Location

Unit Letter O : 330 Feet From The South Line and 2310 Feet From The East Line

Section 7

Township 18-S

Range 28-E

NMPM

Eddy

County

10. Elevation (Show whether DP, RKB, RT, GR, etc.)

3604' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9-9-92: Notify NMOCD @ 9:10 am TX 9-8-92 to Mike Williams about commencing work. MIRU. Nipple down tbg tree 2-7/8" tbg parted approx. 1 ft below slips. NU BOP.

9-10-92: PU & GIH w/4-11/16 overshot w/2-7/8" graffel on 2-7/8" workstring. Tag top of fish @ 713' KB. Attempt to work pkr free. POOH w/workstring to fish. Scanolog tbg. POOH w/108 jts of 2-7/8" tbg. PBTD @ 4089' total inj tbg 3388 ft.

9-11-92: GIH w/bit & scraper on 2-7/8" workstring. Tag fill @ 4038'. Drill fill from 4038' to 4067' (iron sulfide scale). Circ. hole clean w/FW. POOH w/bit & scraper. GIH w/5-1/2 X 2-3/8 pkr, 2-3/8 X 2-7/8 swedge, 2-7/8 SN & 2-7/8 workstring. Set pkr @ 3359'. Press test csg to 3000 psi - OK. Acidize Lower San Andres perms 3410' to 4060' w/6000 gal NEFe 28% HCl.

9-12-92: Release pkr. GIH to 4067'. POOH & LD workstring & pkr. GIH w/5-1/2 X 2-3/8 new Baker Nickle Plated AD-1 pkr & 2-7/8 tbg to 3346'. Tst tbg to

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

(Over)

SIGNATURE

TITLE Agent

DATE 9/22/92

TYPE OR PRINT NAME

L. M. Sanders

915/
TELEPHONE NO. 368-1488

(This space for State Use)

ORIGINAL SIGNED BY

MIKE WILLIAMS

SUPERVISOR, DISTRICT II

APPROVED BY

TITLE

DATE

OCT 2 1992

CONDITIONS OF APPROVAL, IF ANY:

5000 psi. GIH. Pump 70 bbls of 10# brine w/55 gal per 100 bbl, pkr fluid. Set pkr @ 3346'. Test tbg-csg annulus to 520 psi for 30 min. NMOCD Rep. John Robinson on location to witness test. Left well ready for inj.