

c/51

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND RECORDS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

AUG 28 1985

1. oil ☒ gas ☐  
well well

other

O. C. D.

2. NAME OF OPERATOR

Ray Westall

ARTESIA, OFFICE

3. ADDRESS OF OPERATOR

P.O. Box 4 Loco Hills, NM 88255

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 1980 FSL & 2310 FWL

AT TOP PROD. INTERVAL: Same

AT TOTAL DEPTH: Same

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON\* ☐

(other) Spud, 8 5/8", T.D., 5 1/2" csg.

5. LEASE

NM 06245

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Trigg Federal

9. WELL NO.

1

10. FIELD OR WILDCAT NAME

Und. Shugart - Y-SR-Q-G

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

S-35, T-18S, R-30E

12. COUNTY OR PARISH

Eddy

13. STATE

N.M.

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)

3429. GR

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

8-12-85 Spud 12 1/4" hole @ 5:00 P.M.

Ran 12 jts. 477.17' J-55, 24# 8 5/8" casing. Set & cemented @ 488' w/300 sxs Class "C" 2% CaCl. Circulated 50 sxs. Plug down @ 3:45 A.M. 8-13-85. WOC.

8-18-85 T.D. @ 3405'.

8-19-85 Ran 83 jts. 3436.15' 15.5# 5 1/2" casing. Set & cemented @ 3405' w/100 sxs C Thickset 10# salt, 250 sxs Halliburton Lite Class "C" 10# salt, 750 sxs Halliburton Lite Class "C" 15# salt, 400 sxs Class "C" 6# salt. Plug down @ 12:00 A.M. Jet pits. Hold tension on casing.

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Ray Westall TITLE Operator DATE 8-21-85

(This space for Federal or State office use)

APPROVED BY ACCEPTED FOR RECORD TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

AUG 23 1985

\*See Instructions on Reverse Side

CARISBAD, NEW MEXICO