

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
310 Old Santa Fe Trail, Room 206
Santa Fe, New Mexico 87503

WELL API NO.

30-015-189T 25350

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

E - 9261

7. Lease Name or Unit Agreement Name

Midstream "16" State Com.

8. Well No.

1

9. Pool name or Wildcat

Illinois Camp North

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

Mewbourne Oil Company

3. Address of Operator

P.O. Box 5270 Hobbs, New Mexico 88241

4. Well Location

Unit Letter L : 2310 Feet From The South Line and 990 Feet From The West Line

Section 16

Township 18S

Range 28E

NMPM

Eddy

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3617' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MIRU PU. Set CIBP @ 6475' and cap with 35' cement. Load hole with 25#/bbl. brine and salt gel. Spot 25 sx. plug @ 4400'. Attempt 5-1/2" casing cut off @ 3100'. Spot a 100' plug across casing stub and tag cement. Spot 25 sx. plug @ 2780' and tag. Spot 25 sx. plugs @ 1000' and 460'. Set 10 sx. surface plug. Set dry hole marker, cut anchors and clean location. Will notify OCD 24 hours before starting.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE Engineer

DATE 3/30/95

TYPE OR PRINT NAME

Gregory Milner

TELEPHONE NO. (505) 393-5905

(This space for State Use)

APPROVED BY

TITLE Field Rep II

DATE 4-3-95

CONDITIONS OF APPROVAL, IF ANY: