

DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT  
CONS. COMMISSION

EXP. DATE 01, 1985  
5. LEASE DESIGNATION AND SERIAL NO.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen a well in a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Harvey E. Yates Company

3. ADDRESS OF OPERATOR

P.O. Box 1933 Roswell, New Mexico 88201

4. LOCATION OF WELL (Report location clearly and in accordance with State requirements. See also space 17 below.)

At surface

660' FS & EL

RECEIVED BY

FEB 24 1986

O. C. D.  
SARTEBA, OFFICE

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Loco Sand Hills 9 Federal

9. WELL NO.

10. FIELD AND POOL, OR WILDCAT

Wildcat - Bone Springs

11. SEC., T., R., M., OR BLM. AND SURVEY OR AREA

Sec. 9 T-18S R-30E

12. COUNTY OR PARISH 13. STATE

Eddy

N.M.

14. PERMIT NO.

30-015-25498

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3496 GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON\*

SHOOTING OR ACIDIZING

ABANDONMENT\*

REPAIR WELL

CHANGE PLANS

(Other) Completion

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1-15-86 perforate @ 9140-44 (2SPF)

swab test

1-16-86 Perforate @ 9090-92 & 9096-9103 (2SPF)

swab test

1-18-86 Set CIBP @ 9080. Put 35' cement on top (new PBTD @ 9045)

1-20-86 Perforate @ 8648-53 (2SPF)

Acidize w/250 Gal 15% acid. Swab test.

1-22-86 Set CIBP @ 8635 & put 10' cement (New PBTD @ 8625)

Perforate @ 7713-8220 (1SPF)

1-23-86 Acidize w/5000 Gal 7 1/2% acid & swab test.

1-28-86 Perforate 7142-7497 (1SPF) Acidize w/5000 Gal 7 1/2% acid.

1-31-86 Frac w/82,500 Gal BS-60 & 218,000# 20/40 Sand.

Swab test.

2-10-86 Put on production

ACCEPTED FOR RECORD

FEB 19 1986

CARLSBAD, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

NM Young

TITLE Drilling Superintendent

DATE 2-12-86

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side