## STATE OF NEW MEXICO ENERGY AND MINITIALS DEPARTMENT

DISTRIBUTION  SANTA FE  FILE.  U.S.G.E.  LAND DEFICE  OPERATOR	WB. OF COMICS RESESSED	1
U.S.Q.E. LAND OFFICE	DISTRIBUTION	
U.S.G.E.	SANTA FE	1
LAND OFFICE	P 11. E	11
·	U.S.a.s.	
DPERATOR	LAND OFFICE	
	DPERATOR	

) ] [1] - [

ws. s/ (s-1/s		OIL CONSER	ID NOITAVS	VISION	
DISTRIB	JTION		. DOX 2088		Form C-10
SANTAFE			NEW MEXICO	87501	Revised 1
P11.E.		-•		0/301	
U.S.O.E.					Su. Indicate Type of Lease
DPERATOR	<u> </u>				State X Fin
DELATION					5, State Oil & Gus Leuse No.
				. <u>.</u>	LG-4524
lbe ver un	SUNDRY NO	TICES AND REPORTS	ON WELLS		
(170 #01 031	USE "APPLICATION FO	S TO DRILL OR TO DEFPEN ON I H PERMIT —"" (FORM C-101) FO	PLUG BACK TO A DIFFER	TENT RESERVOIR.	
01.					7. Unit Agreement Name
WELL BL		HER-			
2, Name of Operator				21/	8. Farm or Lease Name
Steve Se	√ 11 د		RECEIVE	D BA	1 _
J. Address of Opera	ior				Cal-Mon
D O B	v 5061 Midl	and, Texas 7970	FEB 19	1987	1
14. Location of Well			<del></del>		# 2
	1.05	) FEET PROM THE SC	1 o. c.	0	10. Field and Pool, or Wildcut
UNIT LETTER		FEET PROM THE SC	htn sweeth	330	Loco Hills, Q, GR, S
1					
THE Wes	ST LINE, SECTION	16 TOWNSHIP	18S		
1				- MMPN	
		15. Elevation (Show wh	ether DF, RT, GR, et	:c.)	12. County
		3531	Grd.		Eddy
it.	Check Appre		<del></del>		
	NOTICE OF INTEN	priate Box To Indica	te Nature of Not	tice, Report or Or	her Data
	NOTICE OF INTEN	HON TO:		SUBSEQUEN	T REPORT OF:
				<del></del>	
PERFORM REMEDIAL Y	<b>=</b>	PLUG AND ABANDON	MEMEDIAL WOR	х 📋	ALTERING CARING
TEMPORARILY ABANDO	<del>}==</del> {		COMMENCE DRI	LLING OPNS,	PLUG AND ARANDONIUM
PULL OR ALTER CASIN	٠	CHANGE PLANS	CASING TEST A	HO CEMENT JOB	
			OTHER		
OTHER				•	
17 Da to					
work) SEE RULI	Ki of Completed Operation E 1103.	s (Clearly state all pertinent	t details, and give pe	ertinent dates, including	s estimated date of starting they pro
1 15 05			•		
1-15-8/	Casing would	not pressure t	est.		
1-19-87	Locate leaks.	Back off cas	ing at 300 <b>'</b>	' at replace	two split jts.
1-20-87	Pressure test	casing to 150	0# for 30 m	ninutes. He	ld fine.
1-21-87	Drill cement	from 2608' to	2960'.		
1-22-87	Run CBL and p	ressure test c	asing agair	n. Held fin	e.
1-30-87	Peforate 2228	'-2558' with 1	0 shots. A	Acidize and	frac well.
1-31-87	Flow well bac	k and place we	ll on the r	oump.	
		<u>.</u> — — — — — —	<b>r</b>	· True	
	•				
•					
:					

18. I horeby certify that the	information above is true and	complete to the best of my knowledge and belie	1.
NICHEO Church	Minga	Agent	2-19-87
APPROVED BY	Original Sig Mike Wi Oil & Gas I	lliams	FEB 2 4 1987