

Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

CIST up-1

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

DISTRICT II P.O. Drawer DD, Artesia, NM 88210

DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION P.O. Box 2088 Santa Fe, New Mexico 87504-2088

JAN 22 1992

WELL API NO.
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-11726
7. Lease Name or Unit Agreement Name Loco Hills State
8. Well No. #1
9. Pool name or Wildcat Artesia QN-GB-SA

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL GAS WELL OTHER

2. Name of Operator
Mack Energy Corporation

3. Address of Operator
P.O. Box 276, Artesia, NM 88211-0276

4. Well Location
Unit Letter L : 330 Feet From The West Line and 2260 Feet From The South Line
Section 25 Township 18S Range 28E NMPM Eddy County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3947' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	PLUG AND ABANDONMENT <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to Plug & Abandon as follows:

Set CIBP at 1100'. Spot 15' cement on top of plug. Set mud up to 400'. Set 25 sacks to plug at 400' and 10 sacks to plug at surface. Install dry hole marker. Clean and level location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.
SIGNATURE Mark C. Chase TITLE President DATE 1/17/92

TYPE OR PRINT NAME
(This space for State Use)
APPROVED BY MIKE WILLIAMS TITLE SUPERVISOR, DISTRICT II DATE JAN 22 1992

CONDITIONS OF APPROVAL, IF ANY:
Plugging