Submit 3 Copies State of New Mexico to Appropriate Ene. 57, Minerals and Natural Resources Department District Office OIL CONSERVATION DIVISION	
to Appropriate Ene. 57, Minerals and Natural Resources Department District Office Offi	
DISTRICT OIL CONSERVATION DIVISION	Form C-103
P.O. Box 1980, Hobbs, NM 88240	
P.O. Box 2088 DISTRICT II Santa Fe, New Mexico 87504-2088	30-015-26065
P.O. Drawer DD, Artesia, NM 88210 Santa T e, New MEXICO 87304-2088 5.	Indicate Type of Lease STATE FEE
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410 6. :	State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	B-110831
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUC PACK TO A	Lease Name or Unit Agreement Name
1. Type of Well:	
2 Name of Operator 1	Pierre AGF State Com Well No.
YATES PETROLEUM CORPORATION $\rho_{\alpha}^{\gamma \xi} CF_{\mu} = 1$	1
105 South 4th St., Artesia, NM 88210	Pool name or Wildcat Undesignated
4. Well Location	
Unit Letter A :660 Feet From TheNorth Line and660	Feet From The East Line
Section 26 Township 18S Range 27E NMPM	4 Eddy County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3531.2' GR	
11. Check Appropriate Box to Indicate Nature of Notice, Report	t, or Other Data
	UENT REPORT OF:
	ALTERING CASING
	S. D PLUG AND ABANDONMENT
ULL OR ALTER CASING	
OTHER: OTHER: Abandon Morr	row; perforate & acidize X
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including est	timated date of starting any proposed
work) SEE RULE 1103. 7-28-99 - Moved in and rigged up pulling unit. Nippled down t	
Released packer. TOOH with tubing and packer. Rigged up wire	line. TIH with gauge
ring to 10050'. TOOH with gauge ring. TIH with $4-1/2''$ CIBP ϵ	and set CIBP at 10000'.
Capped CIBP with 35' of cement. Loaded and tested CIBP and ca 7-29-99 - Rigged up wireline. TIH with casing guns and perfor	asing to 500 psi.
.58" holes as follows: 8779-8789', 8893-8895', 8858-8862', 88	366, 67, 71, 9019, 20.
21, 23, 39, 31 & 9219-9221' (1 SPF - Strawn). TOOH wtih casir	ng guns and rigged down
wireline. TIH with RBP, packer and tubing. Straddled perfora	itions 9019-9221' and
acidized with 200 gallons 15% HCL acid and ball sealers. Move perforations 8858-8895'. Acidized with 100 gallons 15% HCL ac	ed tools and straddled
communicated with upper perfs. Moved packer to 8711'. Acidiz	red perforations 8779-8895!
with 3000 gallons 15% iron control HCL acid and ball sealers.	Moved RBP to 9291' and
packer at 8711'. Swabbed.	
7-30-99 - Pumped 30 bbls 2% KCL water. Released packer. TOOH	l with tubing, packer & RBP. NUED ON NEXT PAGE:
I hereby certify that the information above is true and complete to the best of my knowledge and belief. CONTIN	ician July 30, 1999
Operations Techn	
Rusty Kloin	
TYPE OR PRINT NAME Rusty Klein	
TYPE OR PRINT NAME Rusty Klein (This space for State Use) ON SHELL GROWED BY THM WAGUN	теlерноме но. 505/748-147
TYPE OR PRINT NAME Rusty Klein	DATE _9419 90, 1999 ТЕLЕРНОМЕ NO. 505/748-147 DATE 8-4-99