Form 3160-5 (November 1983) (Formerly 9-331) DEPARTMENT OF THE BUREAU OF LAND MAN SUNDRY NOTICES AND RE (Do not use this form for proposals to drill or to dec Use "APPLICATION FOR PERMIT." 1. OIL WELL WELL OTHER Harvey E. Yates Company 3. ADDRESS OF OPERATOR P.O. Box 1933, Roswell, N.M. 8820 4. LOCATION OF WELL (Report location clearly and in accordance See also space 17 below.) At Burface Unit E; 660' FWL.	E INTERIOR (other luarrections on respectively) PORTS ON WELLS epen or plug back to a different reservoir. PECEIVED O. C. D. O.	
·	how whether DF, RT, GR, etc.) 3656 GL	Sec. 8, T18S, R31E 12. COUNTY OF PARISH 13. STATE Fddy N.M.
	o Indicate Nature of Notice, Report, or	
TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly Sta	FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) isolate t (Note: Report result the support of the support result to the support res	ALTERING CASING ABANDONMENT* hief zone ts of multiple completion on Well pletion Report and Log form.)
12/16/90 Set pkr @ 7587'; te 12/18/90 Flow test well 12/19/90 Put well back on pro		erfs 7749, 7755 & 7765
18. I hereby certify that the foregoing is true and correct SIGNED V. Teel	TITLE Production Analyst	DATE _7/11/91
(This space for Federal or State office use) APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	TITLE	3 1991 \$35