

HALLIBURTON SERVICES
ARTESIA DISTRICT

RECEIVED MAY 18 1990


LABORATORY REPORT

No. W282-90TO Yates Energy
Suite 919 - Sunwest Centre
Roswell, NM 88201Date May 16, 1990

This report is the property of Halliburton Services and neither it nor any part thereof, nor a copy thereof is to be published or disclosed without first securing the express written approval of laboratory management. It may however, be used in the course of regular business operations by any person or concern and employees thereof receiving such report from Halliburton Services

Submitted by Gene PrintzDate Rec. May 16, 1990Well No. Thorn Bush Fed. #1 Depth 4670' Formation San Andres
Field Sec. 1, T 18S, R 31E County Eddy Source Tank BatteryResistivity 0.051 @ 75°Specific Gravity .. 1.129pH 6.75Calcium 12,444Magnesium 3,552Chlorides 114,000Sulfates 1,000Bicarbonates 397Soluble Iron 0Potassium 500API Gravity 38.2°KCL 0

Remarks:


Respectfully submittedAnalyst: Rocky Chambers - Field Engineer

HALLIBURTON SERVICES

NOTICE:

This report is for information only and the content is limited to the sample described. Halliburton makes no warranties, express or implied, as to the accuracy of the contents or results. Any user of this report agrees Halliburton shall not be liable for any loss or damage, regardless of cause, including any act or omission of Halliburton, resulting from the use hereof