

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED

Budget Bureau No. 1004-0135

Expires: March 31, 1993

5. Lease Designation and Serial No.

LC-029388D

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

MESQUITE 3 FED. # 3

9. API Well No.

30-015-26275

10. Field and Pool, or Exploratory Area

SHUGART BONE SPRING, NORTH

11. County or Parish, State

EDDY CO., NM

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to deepen or reentry to a different reservoir
Use "APPLICATION FOR PERMIT-" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Harvey E. Yates Company

3. Address and Telephone No.

P.O. Box 1993, Roswell, NM 88202 1-505-623-6601 APR 10 1997

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

990' FS & EL
SEC. 3, T-18S, R-31E

12. CHECK APPROPRIATE BOX(es) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☒ Notice of Intent

☐ Subsequent Report

☐ Final Abandonment

☐ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☒ Other

PLUG & ABANDONMENT

☐ Change in Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut-Off

☐ Conversion to Injection

☐ Dispose Water

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log Form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. GIH w/ 5 1/2" CIBP & SET AT 7425' +/- PLUS 50' CMT.
2. FREE POINT & ATTEMPT TO CUT CSG @ 6000'. POOH. LAY DOWN CSG.
3. GIH w/ TBG TO 50' INSIDE CUT OFF STUB. SPOT 100' PLUG (50' IN & 50' OUT).
4. PULL TBG TO 3650' (TOP OF GRAYBURG) & SPOT 100' PLUG.
5. PULL TBG TO 2370' (50' BELOW INTERM. SHOE) & SPOT 150' PLUG.
6. PULL TBG TO 400' (50' BELOW SURFACE SHOE) & SPOT 100' PLUG.
7. CUT OFF WELL HEAD
8. RUN TBG TO 50' AND SPOT SURFACE PLUG.
9. INSTALL DRY HOLE MARKER. BACK FILL ALL PITTS & CLEAN UP LOCATION.

PIT TO BE DUG AND FENCED FOR OPERATIONS BUT BACKFILLED AFTER P&A COMPLETED.

14. I hereby certify that the foregoing is true and correct

Signed

Ray F. Nokes

RAY F. NOKES

Title

PROD. MGR./ ENG.

Date

4/8/97

(This space for Federal or State office use)

(ORIG. SGD.) DAVID R. GLASS

Approved by

Title

PETROLEUM ENGINEER

Date

APR 14 1997

Conditions of approval, if any:

This 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

* See Instruction on the Reverse Side

APPROVED FOR
CONDITIONS OF APPROVAL

C/SF

RECEIVED

APR 10 1997

BLM
ROSWELL, NM