

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. Oil Co. Division
311 S. 1st Street
Artesia, NM 88210-2834

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

C/SF

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir
Use "APPLICATION FOR PERMIT--" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Harvey E. Yates Company

3. Address and Telephone No.

P.O. Box 1993, Roswell, NM 88202 1-505-623-6601

4. Location of Well (Footage, Sec., T., R., M, or Survey Description)

990' FS & EL
SEC. 3, T-18S, R-31E

5. Lease Designation and Serial No.

LC-029388D

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

MESQUITE 3 FED. # 3

9. API Well No.

30-015-26275

10. Field and Pool, or Exploratory Area

SHUGART BONE SPRING, N.

11. County or Parish, State

EDDY CO., NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing

☒ Other PLUG & ABANDONMENT

- ☐ Change in Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log Form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

CURRENT PERFS: 7467-81'

TOC @ 6018' PER CBL

- GIH w/ 5 1/2" CIBP & SET AT 7425' +/- PLUS 50' CMT.
- FREE POINT & ATTEMPT TO CUT CSG @ 5500 TO 6000'. POOH. LAY DOWN CSG.
- GIH w/ TBG TO 50' INSIDE CUT OFF STUB. SPOT 100' PLUG (50' IN & 50' OUT). TAG
- PULL TBG TO 3650' (TOP OF GRAYBURG) & SPOT 100' PLUG.
- PULL TBG TO 2370' (50' BELOW INTERM. SHOE) & SPOT 100' PLUG. TAG
- PULL TBG TO 400' (50' BELOW SURFACE SHOE) & SPOT 100' PLUG.
- CUT OFF WELL HEAD
- RUN TBG TO 50' AND SPOT SURFACE PLUG.
- INSTALL DRY HOLE MARKER. BACK FILL ALL PITS & CLEAN UP LOCATION.

PIT TO BE DUG FOR OPERATIONS BUT BACKFILLED AFTER P&A COMPLETED.

14. I hereby certify that the foregoing is true and correct

Signed

Ray F. Nokes

RAY F. NOKES

Title

PROD. MGR./ ENG.

Date

11/10/99

(This space for Federal or State office use)

Approved by

Record Only

Title

Date

Conditions of approval, if any:

This 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

* See Intruction on the Reverse Side



