CRA BLM FORMAT

OFF LEASE STORAGE AND MEASUREMENT APPROVAL

This Format Should Be Attached To A Sundry Notice

To: Bureau of Land Management P. O. Box 1778 Carlsbad, New Mexico 88221-1778

<u>Mewbourne Oil Company</u> (Operator's Name) is requesting approval for surface commingling and off-lease storage and measurement of hydrocarbon production from the following formation(s) and well(s) on Federal Lease No. <u>NM-0557371</u>; Lease Name: <u>Chalk Bluff Federal</u>

Well No.	Loc.	Sec.	Twp.	Rng.	Formation
<u>#2</u> <u>#3</u>	F		<u>_185</u>	<u>27E</u> 27E	Morrow
					<u></u>

with hydrocarbon production from the following formation(s) and well(s) on State lease No. $\frac{E-7179}{E-647}$; Lease Name: <u>Chalk Bluff</u>"6"

	E-647 E-1313				Illinois Camp 17 Illinois Camp 20	
Well No.	Loc.	Sec.	Twp.	Rng.	Formation	
Chalk Bluff 6 St. #1 Illinois Camp 17 St. #1 Illinois Camp 17 St. #2 Illinois Camp 20 St. #1	M F J C	6 17 17 20	<u>185</u> <u>185</u> 185 185	28E 28E 28E 28E	Morrow Morrow Morrow	

Production from the wells involved is as follows:

Well Name and No.	BOPD	Oil Gravity	MCFPD
Chalk Bluff Fed. #2	N/A	<u>N/A</u>	80
Chalk Bluff Fed. #3 Chalk Bluff 6 St. #1	N/A N/A	<u> </u>	<u> </u>
Illinois Camp 17 St. #1 Illinois Camp 17 St. #2	<u>N/A</u>	<u> </u>	1 <u>200</u>
Illinois Camp 20 St. #1	<u>N/A</u>	<u> </u>	<u>118</u>

* Only gas will be comingled off lease

Continued ...

U.

5

5

11 - 15 - 15 - 15