	TINT	TED STATES	rawer D	NM 88210 APPROVED
Form 3160-5 (June 1990)		T OF THE INTERIOR	Artebies	Budget Bureau 190 1004-0135
(June 1990)		LAND MANAGEMENT	5	Expires. March 31, 1993 Lease Designation and Serial No.
			NM 86107	
SUNDRY NOTICES AND REPORTS ON WELLS				If Indian, Allottee or Tribe Name
Do not	use this form for proposals to dr	ill or to deepen or reentry to a different re R PERMIT—" for such proposals	eservoir.	
			,	. If Unit or CA, Agreement Designation
SUBMIT IN TRIPLICATE				, ,, e.u. e. e.u, ng. e.u e.g e.g.
1. Type of Well			8	Well Name and No.
Oil Well Gas Well Other				Kaiser Lake Federal #1
Mewbourne Oil Company			9.	API Well No.
3. Address and Telephone No.				30-015-26779 Field and Pool, or Exploratory Area
P.O. Box 5270 Hobbs, New Mexico 88241 (505) 393-5905 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				Lake East Morrow
4. Location of Well (Footage, Sec., 1., K., M., 6) Survey Description) Surface: 1650' FSL & 1650' FEL			11	County or Parish, State
TD: 1356' FSL & 2012' FWL				
	Sec. 32-T18S-R27E		the second s	Eddy Co. N.M.
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA				
	TYPE OF SUBMISSION TYPE OF ACTION			
	Notice of Intent	Abandonment		Change of Plans
				New Construction
	Subsequent Report	Plugging Back		Water Shut-Off
	Final Abandonment Notice	Altering Casing		Conversion to Injection
		Other		Dispose Water (Note: Report results of multiple completion on Well
		the second s		Completion or Rec. mpletion Report and Log form.)
13. Describe give	e Proposed or Completed Operations (Clearly state a e subsurface locations and measured and true vert	Il pertinent details, and give pertinent dates, including estimated cal depths for all markers and zones pertinent to this work.)*	date of starting any	proposed work in wear is encedonally district,
Mew	bourne Oil Company propos	es plugging procedure as follow	ws:	
	arph 6 0600' and cap wit	h 35' cement. Set 100' cement	plugs @ 9	9410'-9310';
z = z = z = z = z = z = z = z = z = z =				
8280'-8180'; 7285'-7185'. Should off 9 7/2 'casing c 5100' - 2880'; 450'-350'. casing. Set cement plugs @ 5050'-5150', 4400'-4300'; 2780'-2880'; 450'-350'. Set 10 sx. surface plug cut off wellhead and install P & A marker. Clean				
Set	10 sx. surface plug cut	hrs. before operations begin.	marker.	Clean
loc	ation, will notify buy 2.		SMR	
			eivei	
			<u>^</u>	
		SEP.	0 8 1995	
		OIL CO		
		EDA	ST. 2	and the second s
				<u></u>
	by certify that the foregoing is true and correct			
Signed	In Man	Title Engineer	,	Date August 8, 1995
(This s	pace for Federal or State office use)		012/2mm	9/2/00-
Approved by ORIG SOD 1070 LONG PETROLEUM ENGINEER Date 9/5/95				
Conditions of approval, if any: See attached. Also, tag, plugs @ 51/2" cisg stub + 8 5/8" cisg stue.				
Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements				
or represen	stations as to any matter within its jurisdiction.			
*See Instruction on Reverse Side				