

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-015-26869
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E-7989
7. Lease Name or Unit Agreement Name Red Lake State
8. Well No. 1
9. Pool name or Wildcat Atoka - Red Lake

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☐

GAS
WELL ☒

OTHER

2. Name of Operator

Mewbourne Oil Company

3. Address of Operator

P.O. Box 5270 Hobbs, New Mexico 88241

4. Well Location

Unit Letter N : 1980 Feet From The West Line and 990 Feet From The South Line

Section 16

Township 18S

Range 27E

NMPM

Eddy

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3449' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Set 5-1/2" CIBP at \pm 9130'. Cut with 35' cement.
- Set 100' cement plug at 6420'. (Top of Penn)
- Set 100' cement plug at 4240'. (Top of Tubb)
- Set 100' cement plug at 1850' (8-5/8" csg. set at 1800'). Tag with tbg.
- Set 100' cement plug at 900' (Top of Queen)
- Set 100' cement plug at 446' (13-3/8" set at 396')
- Cut off wellhead and set 10 sx. plug.
- Install P & A marker and clean location.

* Records show long string cemented to surface. If it is determined that there is recoverable casing, we will cut it off and notify NMOC.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Erick W. Nelson

TITLE

Engineer

DATE April 5, 1994
(505)

TYPE OR PRINT NAME

Erick W. Nelson

TELEPHONE NO. 393-5905

(This space for State Use)

SUPERVISOR DISTRICT II

APR 25 1994