

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

# OIL CONSERVATION DIVISION

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

MAR 24 1992

O. C. D.  
ARTESIA OFFICE

WELL API NO.	30-015-26895
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	703
7. Lease Name or Unit Agreement Name	Levers A State
8. Well No.	2
9. Pool name or Wildcat	Artesia (Queen, Grayburg, S.A.)

<p><b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)</p>	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator Plains Petroleum Operating Company	
3. Address of Operator 415 West Wall, Suite 1000 Midland, Texas 79701	
4. Well Location Unit Letter <u>B</u> : <u>330</u> Feet From The <u>N</u> Line and <u>2310</u> Feet From The <u>E</u> Line Section <u>8</u> Township <u>18S</u> Range <u>28E</u> NMPM <u>Eddy</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) Gr 3633'	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
<p><b>NOTICE OF INTENTION TO:</b></p> <p>PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/></p> <p>TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/></p> <p>PULL OR ALTER CASING <input type="checkbox"/></p> <p>OTHER: <input type="checkbox"/></p>	<p><b>SUBSEQUENT REPORT OF:</b></p> <p>REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/></p> <p>COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/></p> <p>CASING TEST AND CEMENT JOB <input type="checkbox"/></p> <p>OTHER: Run pump, rods, etc. <input checked="" type="checkbox"/></p>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1-13-92 RIH w/2-7/8" EUE tbg, 4' perf sub, SN, 2-1/2" x 1-1/2" x 10' pump. Set & balance American 114D beam unit w/20 HP motor & start pumping.

1-18-92 Well pumped off - pulled

1-24-92 Install electrical power supply. Reran pump

1-30-92 POOH w/2-7/8" tbg & set pkr @ 2193'. Acidize perfs 2216'-2269' w/5000 gal 3% NEFE HCl, 12 bbl 2% KCL flush. Circ w/36 bbls 2% KCL. Treat perfs (Set RBP @ 2193') 1955'-2059' w/3000 gal 2% KCL w/clay stabilizer, surfactant & gel breaker flush. Set RBP @ 1815', set pkr @ 1657'. Treat perfs 1712'-1716' w/2000 gal 2% KCL w/clay stabilizer, surfactant & gel breaker. Flush w/11 bbls 2% KCL. Release pkr. TIH & tag up @ 1813', Circ hole W/6 bbls 2% KCL Release RBP.

1-31-92 Ran 2-7/8" tbg, 2-1/2" x 1-1/2" x 10' pump, rods. Hung on w/good pump action.

2-02-92 Not pumping, clogged w/gelled fluid

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bonnie Husband TITLE Office Manager/Tech DATE 03-23-92

TYPE OR PRINT NAME Bonnie Husband TELEPHONE NO. (915) 683-4434

(This space for State Use)

ORIGINAL SIGNED BY  
MIKE WILLIAMS  
SUPERVISOR, DISTRICT II

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE MAR 26 1992

CONDITIONS OF APPROVAL, IF ANY:

C - 103 Cont.

12.

2-03-92	Pull & rerun pump
2-18-92	Built prod. battery w/3' x 15' 3 phase vertical sep, 210 bbl wtr tank & 2-210 bbl oil tanks
2-27-92	Unseat pump, POOH w/rods & pump. GA 80% plugged w/gel & sand. Inspect MA, no fill. Perf'd sub ports open. Ran pump, rods & space.
3-04-92	Tried producing well on 50% time clock, unsuccessfully. Return to full time.