

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

JUN - 9 1992

WELL API NO. 30-015-26896
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. 703
7. Lease Name or Unit Agreement Name LEVERS A STATE
8. Well No. 3
9. Pool name or Wildcat Artesia (QGSA)
10. Elevation (Show whether DF, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Plains Petroleum Operating Company
3. Address of Operator 415 West Wall, Suite 1000 Midland, Texas 79701	4. Well Location Unit Letter B : 990 Feet From The North Line and 1650 Feet From The East Line Section 8 Township 18S Range 28E NMPM Eddy County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-30-92 Spud 12 1/4" hole (Capstar Drlg. Co.). Ran 8 jts 8 5/8" 24# j-55 csg. Set @ 365' w/220 sx "C" w/2% CaCl. Displace w/20 BFW. Circ 20 sx to surf. WOC 10 hr. NU BOP 1/2 hr - held ok.

5-5-92 PBTD 2554' 7 7/8" hole. Ran 5 1/2" 14# J-55 csg to 2500'. Cmt w/395 sx "C" w/50:50 poz & lite. Displace plug w/60 bbl 2% KCL. Press up BOP - held ok. 13 hr WOC. Float held. Rig released 6pm 5-5-92. Ran temp survey, TOC @ 600' FS.

5-11-92 Install guyline anchors. NU BOP. Ran 2 3/8" tbg to 2294. Spot 250 gal 15% NEFE HCL from 2294' - 2044'. Perf 1-SPF @ 2233 - 2292 (20 holes) Acidize w/750 gal NEFE HCL & 57 bbls 2% KCL flush. Frac w/7000 gal gel pad. 35000# 12/20 Brady Sd.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bonnie Husband TITLE Office Manager/Tech DATE 06-08-92

TYPE OR PRINT NAME Bonnie Husband TELEPHONE NO. (915) 683-4434

(This space for State Use) ORIGINAL SIGNED BY  
MIKE WILLIAMS  
APPROVED BY SUPERVISOR, DISTRICT II TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY: \_\_\_\_\_

JUN 16 1992