

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
310 Old Santa Fe Trail, Room 206
Santa Fe, New Mexico 87503

WELL API NO. 30-015-27009	
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil & Gas Lease No. E - 1286	
7. Lease Name or Unit Agreement Name Turkey Track "15" State	
8. Well No. 1	
9. Pool name or Wildcat Wildcat - Bone Spring	
10. Elevation (Show whether DF, RRB, RT, GR, etc.) 3597' GR	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	
2. Name of Operator Melbourne Oil Company	
3. Address of Operator P.O. Box 5270 Hobbs, New Mexico 88241	
4. Well Location Unit Letter <u>E</u> : <u>1980</u> Feet From The <u>North</u> Line and <u>990</u> Feet From The <u>West</u> Line Section <u>15</u> Township <u>18S</u> Range <u>28E</u> NMPM <u>Eddy</u> County	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ PULL OR ALTER CASING ☐ OTHER: ☐		SUBSEQUENT REPORT OF: REMEDIAL WORK ☐ ALTERING CASING ☐ COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐ CASING TEST AND CEMENT JOB ☐ OTHER: ☐	
--	--	---	--

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MIRU PU. GIH & tag CIBP @ 7897'. Cap if not capped with cement. Set a 100' plug across DVT @ 7776'. Set CIBP @ 6318' and cap with 35' cement. Load hole with 25#/bbl. salt gel and brine. Spot 25 sx. plugs @ 3655', 2678', 1702', 600', and 390'. Set a 10 sx. surface plug. Set dry hole marker, cut anchors, and clean location. Will notify OCD 24 hours before starting.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Gregory Milner TITLE Engineer DATE 3/28/95
 TYPE OR PRINT NAME Gregory Milner TELEPHONE NO. (505) 393-5905

(This space for State Use)

APPROVED BY Ray Smith TITLE Field Rep II DATE 3-29-95
 CONDITIONS OF APPROVAL, IF ANY: