

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-015-27285
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E-7811
7. Lease Name or Unit Agreement Name Cedar Breaks "2" State
8. Well No. 2
9. Pool name or Wildcat Cedar Lake Strawn
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3594' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Meybourne Oil Company	3. Address of Operator P.O. Box 5270 Hobbs, New Mexico 88241	4. Well Location Unit Letter A : 990 Feet From The North Line and 990 Feet From The East Line Section 2 Township 18S Range 30E NMPM Eddy County
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: Plug back to different reservoir <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-23-94 Set 5-1/2" CIBP at 11,250'. Dump 35' cement on plug. Test to 1000#.
Set 5-1/2" CIBP at 10,710'. Dump 35' cement on plug.
5-24-94 Perforate Strawn from 10,472'-10,486'.
5-30-94 Acidize Strawn with 3000 gal. 15% HCL acid.
6-01-94 Acidize Strawn with 20000 gal. gelled 20% HCL acid
6-04-94 TIH w/tbg. string & rods. Installed surface equipment.
6-10-94 Restore well to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Erick W. Nelson TITLE Engineer DATE 06-21-94
(505)
TYPE OR PRINT NAME Erick W. Nelson TELEPHONE NO. 393-5905

(This space for State Use)

SUPERVISOR, DISTRICT II

JUL 8 1994

