to Appropriate Elicity, minicials and realistic Resolution 20pm-	-161
DISTRICT I P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088	WELL API NO. 30-015-27461
DISTRICT II P.O. Drawer DD, Antesia, NM 88210 Santa Fe, New Mexico 87504-2088.	5. Indicate Type of Lease STATE FEE X
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410 JUL 1 9 1993	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS C. C. D. ( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name
1. Type of Well: OL OAS WELL WELL XX OTHER	Vandiver AIM
2 Name of Operator YATES PETROLEUM CORPORATION	8. Well No. 2
3. Address of Operator	9. Pool name or Wildcat West Atoka Morrow
4. Well Location         Unit LetterG: _2091Feet From TheNorthLine andT63Feet From TheLine	
Section         17         Township         18S         Range         26E         NMPM         Eddy         County           10. Elevation (Show whether DF, RKB, RT, GR, etc.)         3387'         3387'         3387'         3387'	
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT	
PULL OR ALTER CASING	
<ul> <li>12. Describe Proposed or Completed Operations (Clearly state all periment details, and give periment dates, including estimated date of staring any proposed work) SEE RULE 1103.</li> <li>TD 1300'. Ran 29 joints of 9-5/8" 36# J-55 (1299.83') of casing set at 1300'. 1-regular guide shoe set at 1300'. Float collar set at 1255'. Cemented with 200 sacks "H", 12% Thixad, 10# gilsonite, 1/2#/sack celloseal and 2% CaCl2 (yield 1.55, weight 14.6). Tailed in with 400 sacks Pacesetter Lite "C", 5#/sack gilsonite, 1/4#/sack celloseal and 3% CaCl2 (yield 1.98, weight 12.4) and 200 sacks "C" 2% CaCl2 (yield 1.32, weight 14.8). PD 8:27 AM 7-3-93. Bumped plug to 800 psi, OK. Cement did not circulate. WOC 3 hours. Ran Temperature Survey and found top of cement at 780'. Ran 1". Tagged cement at 780'. Spotted 50 sacks "C" 3% CaCl2. PD 1:33 PM 7-3-93. WOC 2 hours. Ran 1". Tagged cement at 700'. Spotted 50 sacks "C" 3% CaCl2. PD 3:33 PM 7-3-93. WOC 2 hours. Ran 1". Tagged cement at 670'. Spotted 50 sacks "C" 3% CaCl2. PD 3:33 PM 7-3-93. WOC 2 hours. Ran 1". Tagged cement at 670'. Spotted 50 sacks "C" 3% CaCl2. PD 3:33 PM 7-3-93. WOC 2 hours. Ran 1". Tagged cement at 670'. Spotted 50 sacks "C" 3% CaCl2. PD 3:33 PM 7-3-93. WOC 2 hours. Ran 1". Tagged cement at 670'. Spotted 50 sacks "C" 3% CaCl2. PD 9:00 PM 7-3-93. Circulated cement to surface. WOC. Drilled out 6:15 PM 7-4-93. WOC 33 hours and 50 minutes. Nippled up and tested to 1000# for 15 minutes, OK. Reduced hole to 7-7/8". Resumed drilling.</li> <li>Inereby certify that ha formation above is trye apt formplate to the best of my knowledge and belid.</li> <li>SIONATURE RUST Klein Rust Klein Rust Klein Rust Klein Rust Klein Rust Klein Rust Rust Rust Rust Rust Rust Rust Rust</li></ul>	
(This space for State Use) ORIGINAL SIGNED BY	1000 A - 1000
MIKE WILLIAMS	JUL <u>8 j</u> 1993
APPROVED BY SUPERVISOR, DISTRICT IF TITLE	