

30-015-27461

David - 25525

Prop - 14326

Pop - 70960

142
C+T

Oxford[®]

ESSELTE

MADE IN U.S.A.

NO. R753 1/3

• •

• •

2-21-94

Comp West

350-9050

DLH

1299-9081

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

FEB 21 1994

WELL API NO.

30-015-27461

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☐

GAS
WELL ☒

OTHER

2. Name of Operator

YATES PETROLEUM CORPORATION

3. Address of Operator

105 South 4th St., Artesia, NM 88210

4. Well Location

Unit Letter G : 2091 Feet From The North Line and 1763 Feet From The East Line

Section 17

Township 18S

Range 26E

NMPM

Eddy

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3387'

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

Post FD-2
5-6-94
P4A

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-15-94 - Moved in and rigged up United Oil Service's pulling unit. Notified Ray Smith with the Oil Conservation Division in Artesia. Pulled packer and RBP. Set 5-1/2" CIBP at 6924'. TIH with tubing and tagged RBP at 6924'. Pressured casing to 500 psi for 10 minutes. Spot a 22 sack Class "C" Neat plug from 6924-6674'. Spot 113 bbls plugging mud (25#/barrel salt gel) from 6630'. Pulled tubing up to 5730'. Spotted 25 sacks Class "C" Neat from 5730-5480'. Pulled tubing up to 4430'. Spotted 25 sacks Class "C" Neat from 4430-4180'. Attempted to free point 5-1/2" casing, but could not pull casing off of slips. Consulted with OCD - Artesia (Gary Williams) and obtained approval to cut casing at 2000' and attempt to pull. Cut casing at 2000' but could not pull. Pressured cut to 800 psi. No bleed off. Obtained approval to cut at 1350'. Could not pull. Pressured to 800 psi. No bleed off. TIH w/tubing and spot 25 sacks across each cut (2125-1875' & 1475-1225'). WOC. Tagged shoe plug at 1218'. Perforated 5-1/2" casing at 900'. Pressured up to 1500 psi. Could not pump into to circulate. No bleed off in 10 minutes. Obtained NMOCD approval to spot 25 sacks Class "C" Neat from 1025-775'. Set a 10 sacks Class "C" Neat plug at surface.*

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Rusty Klein

TITLE

Production Clerk

DATE

Feb. 18, 1994

TYPE OR PRINT NAME

Rusty Klein

TELEPHONE NO. 505/748-1471

(This space for State Use)

APPROVED BY

[Signature]

TITLE

[Signature]

DATE

2/6/94

CONDITIONS OF APPROVAL, IF ANY:

* Location will be restored per agreement with landowner. PLUGGED AND ABANDONED - FINAL REPORT.
Plugging complete February 17, 1994.