

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Geology, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

FEB 21 1994

WELL API NO. 30-015-27789
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL ☒ GAS WELL ☐ OTHER P&A

2. Name of Operator  
YATES PETROLEUM CORPORATION

3. Address of Operator  
105 South 4th St., Artesia, NM 88210 (505) 748-1471

4. Well Location  
Unit Letter K : 1980 Feet From The South Line and 1980 Feet From The West Line  
Section 34 Township 18S Range 25E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
3495' GR

7. Lease Name or Unit Agreement Name  Rio Penasco RT
8. Well No. 2
9. Pool name or Wildcat Penasco Wolfcamp

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  
TD 6200'. Reached TD 2-15-94.  
Received plugging order from Mike Stubblefield, NMOCD, Artesia, to plug well as follows:  
Plug 31 5545-5445' with 40 sacks Class "C" Neat.  
Plug #2 4540-4440' with 40 sacks Class "C" Neat.  
Plug #3 2026-1926' with 40 sacks Class "C" Neat.  
Plug #4 1264-1164' with 45 sacks Class "C" Neat with 2% CaCl<sub>2</sub>. WOC 1 hour. Tag cement 1145'.  
Plug #5 540-440' with 30 sacks Class "C" Neat.  
Top of zones: Wolfcamp 5495', Abo 4490', Glorieta 1976', 8-5/8" casing shoe 1214', 13-3/8" casing shoe 490'.  
Nippled down and jet pits. Set regulation abandonment marker. Well plugged and abandoned.  
Rig released 5:00 AM 2-18-94.

Part 5D-2  
4-15-94  
PFA

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 2-21-94

TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)

APPROVED BY Mike Stubblefield TITLE Field Rep I DATE Dec. 10-94

CONDITIONS OF APPROVAL, IF ANY: