Submit 3 Copies to Appropriate District Office	State of New M Energy Clinerals and Natural R	exico Resources Department	Form C-103 Revised 1-1-89	4
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	P.O. Box 2088		WELL API NO. 30-015-28080	ן
DISTRICT II P.O. Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2088		5. Indicate Type of Lease STATE FEE X	. 	
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No.	
	ICES AND REPORTS ON WE			4
(DO NOT USE THIS FORM FOR PF DIFFERENT RESE (FORM	ICES AND REPORTS OF THE ICPOSALS TO DRILL OR TO DEEPE RVOR. USE "APPLICATION FOR P C-101) FOR SUCH PROPOSALS.)	IN OH FLUG BROIL TO A	7. Lease Name or Unit Agreement Name	
1. Type of Well: Of AS WELL XX WELL) OTHER	SEP 19.'94	Ryburn FZ	_
2. Name of Operator			8. Well No. 2	
YATES PETROLEUM CORPO	DRATION	0. C. D.	9. Pool name or Wildcat	-1
3. Address of Operator	et - Artesia, NM 8821	ARTESLA, OFFICE	Undesignated San Andres	_
105 South Fourth Street - Artesia, NM 88210 Undesignated San Andres 4. Well Location 000				
	30 Feet From The South	Line and990	Feet From The	
Section 22	Township 185	Range 26E	NMPM Eddy County	7
Section 22	10. Elevation (Show when 3233'	her DF, RKB, RT, GR, etc.)		
	<u>3233</u>	BR Nature of Notice.	Report, or Other Data	
Information Subscription 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
NOTICE OF I	L L L L L L L L L L L L L L L L L L L	_	ALTERING CASING	
PERFORM REMEDIAL WORK				
	CHANGE PLANS			
PULL OR ALTER CASING	_	CASING TEST AND		x
OTHER:	l		cate, acidize & frac	
 12. Describe Proposed or Completed Operations (Clearly state all perinent data), and give perinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 9-13-94 - Cleaned location, set and tested anchors and markers. Made cut off on 5-1/2" casing and welded on bell nipple. Moved in and rigged up pulling unit. Nippled up tubinghead and installed BOP. TIH w/bit, scraper and 2-7/8" tubing. Tagged at 1770'. Displaced casing with 2% KCL water. Tested casing to 2500 psi,0K. TOOH with 2-7/8" tubing, scraper and bit. Rigged up wireline. TIH with logging tool. Ran GR/CBL/CCL log. TOOH with logging tool. 9-14-94 - TIH w/4" casing guns and perforated 1648-1720' w/20.42" holes (1 SPF) as follows: 1648, 49, 50, 51, 52, 54, 55, 56, 1664, 70, 71, 72, 83, 84, 90, 1703, 04, 10, 18 & 1720'. TOOH with casing guns and rigged down wireline. TIH with packer and 2-7/8" tubing to 1722'. Spotted 2 bbls 20% NEFE acid across perforations. Moved up and set packer at 1560'. Acidized perforations 1648-1720' with 2000 gallons 20% NEFE acid and ball sealers. Unset ¬ packer at 1560'. TOOH with 2-7/8" tubing and packer. Nippled down BOP and tubinghead. Frac'd perforations 1648-1720' (down 5-1/2" casing) with 80000 gallons 35# crosslink gel & 153000# 20-40 Brady sand. Shut down. Thereby certly the up formation above intrue and complete to the best of my knowledge and belief. 				
SIGNATURE TUSH,	<i>p</i>		505-748-1471 TELEPHONE NO.	
TYPE OR PRINT NAME RUSTY K1	ein			
(This space for State Use)			OCT 3 1 199	94
	SOR, DISTRICT 11	TITLE	DATE	
APPROVED BY				