Form 3160-5 (November 1983) (Formerly 9-331)

Tit

## UNITEL TATES **DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT**

SUBMIT IN TRIPLICA . . \* (Other Instructions on reverse side )

Budget Bureau No. 1004-0135 Expires August 31, 1985

BUREAU OF LAND MANAGEMENT	5. LEASE DESIGNATION AND SERIAL NO. NM 98122
SUNDRY NOTICES AND REPORTS ON WELLS	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  Use "APPLICATION FOR PERMIT - " for such proposals.)	
OIL GAS OTHER P&A	7. UNIT AGREEMENT NAME Skelly Unit
2. NAME OF OPERATOR The Wiser Oil Company	8. WELL NAME AND NO. 161
3. ADDRESS OF OPERATOR	9. API NO.
P.O. Box 2568 Hobbs, New Mexico 88240  4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.	30-015-28140 10. FIELD AND POOL, OR WILDCAT
See also space 17 below.)	Grayburg Jackson San Andres
At surface	11. SEC., T., R., M., OR BLK. AND
1650' FSL & 2310' FWL Unit K	SURVEY OR AREA Sec. 28-T17S-R31E
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3788' KB	12. COUNTY OR PARISH 13. STATE Eddy County NM
16. Check Appropriate Box to indicate Nature of Notice, Report, or Ot	ther Data
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
TEST WATER SHUT OFF PULL OR ALTER CASING WATER SHUT-OFF	REPAIRING WELL ALTERING CASING
FRACTURE TREAT  MULTIPLE COMPLETE  FRACTURE TREATMEN	T
SHOOT OR ACIDIZE ABANDON* SHOOTING OR ACIDIZI	ABANDONMENT *
REPAIR WELL CHANGE PLANS (Other) P & A	s of multiple completion on Well
(Other) Completion or Reco	ompletion Report and Log form.)
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS: (Clearly state all pertinent details, and give pertinent da proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for a	ites, including estimated date of starting any Il markers and zones pertinent to this work.)
12/28/01 MIRU Mayo Marrs Casing Pulling Inc. Install WH. RIH w/WL & tag CIBP @ 3588'. OK'D by Jim Amos & Kathy w/BLM. RIH w/tb No tag required per Kathy w/BLM. Spot 35 sks. @ 899'. POH. Tag @ 765'. POH & Spot 35 sks. @ 703'-575'. POH. Perforate @ 5 w/30 sks. All plugs witnessed by Kathy BLM and procedure approved by Kathy & Jim Amos.  12/29/01 Cut off WH. RDMO. Install dry hole marker. Well is P & A.	• •
	RECEIVED OCD - AFTERIA
18. I hereby certify that the foregoing is true and correct.	· -
SIGNED Mary To Turner TITLE Production Tech II	DATE January 12, 2002
(This space for Federal or State office use)	
APPROVED BY TITLE CONDITIONS OF APPROVAL, IF ANY:	DATE
Accepted for record *See Instruction On Reverse Side  Til only ingly and willfully to make to any department or agence	ry of the United States any false, fictitious or fraudulent