

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

M OIL CONS COMMISSION
Drawer DD
Artesia, NM 88210

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

Coastal Management Corporation

3. Address and Telephone No.

PO Box 2726 Midland, Texas 79702 (915) 688-0700

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

950' FSL & 1980' FEL
Sec. 29 T-17s R-31e

5. Lease Designation and Serial No.

LC-029395 B

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Tracy 29 Federal #1

9. API Well No.

30-015-28142

10. Field and Pool, or Exploratory Area

Cedar Lake

11. County or Parish, State

Eddy, New Mexico

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ Other Test Morrow/plugging back
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

12-12-94 MI Completion Equipment. Drill out DV Tool @ 10795'. Clean out to 11778' (PBTD)
12-21-94 Perforate Morrow @ 11628-42 w/2spf. Flow/swab test well.
12-22-94 Acidize w/1000 gals 10% HCL. Flow/swab test well.
12-26-94 Reacidize w/4000 gals 10% HCL & ball sealers. Flow/swab test well.
1-3-95 SWI & run BHPB.
1-18-95 Perforate additional Morrow @ 11544-51 w/2spf. Flow/swab test well.
1-19-95 Acidize Perfs w/1000 gals 7 1/2% hcl. Flow/swab test well.
1-23-95 Reacidize w/2000 gals 10% HCL & N2. Flow/swab test well.
1-27-95 POOH w/ tbg. Set CIBP @ 11350' w/ 35' cement on plug. New PBTD @ 11315'
Will test for production up hole.

RECEIVED

MAR 3 1995

OIL CON. DIV.

14. I hereby certify that the foregoing is true and correct

Signed Larry Snyder for Larry Snyder Title Land Supervisor

Date 1-28-95

(This space for Federal or State office use)

Approved by

Conditions of approval, if any:

Title

Date