

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-015-28879
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	Dayton FP
8. Well No.	2
9. Pool name or Wildcat	Atoka San Andres

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator YATES PETROLEUM CORPORATION	
3. Address of Operator 105 South 4th St., Artesia, NM 88210	
4. Well Location Unit Letter <u>G</u> : <u>1650</u> Feet From The <u>North</u> Line and <u>1750</u> Feet From The <u>East</u> Line Section <u>21</u> Township <u>18S</u> Range <u>26E</u> NMPM Eddy County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3360' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: Perforate, acidize & frac <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-13-15-96 - Cleaned location and set anchors. Moved in and rigged up pulling unit. Rigged up wireline. TIH with logging tools and ran CNL/GR/CCL log. TOOH with logging tools and rigged down wireline. TIH with bit and scraper and tagged PBTD at 1770'. TOOH. Shut in.
4-16-96 - Rigged up wireline. TIH with 4" casing guns and perforated 1569-1626' w/20 .42" holes as follows: 1569, 70, 71, 82 & 1626' (4 SPF). TOOH with casing guns and rigged down wireline. TIH with packer and RBP. Straddled perforation 1626'. Set RBP at 1640'. Spotted 20 bbls 20% NEFE acid. Broke down perforation 1626'. Acidized perforation 1626' with 1000 gallons 20% NEFE acid. Moved tools and straddled perforations 1569-1582'. Breakdown perforations 1569-1582'. Acidized perforations 1569-1582' with 3000 gallons 20% NEFE acid and ball sealers. Bled down and released tools. TOOH with packer and RBP. Nippled down BOP. Nippled up 4-1/2" frac valve. Shut in.
4-17-96 - Frac'd perforations 1569-1626' with 100000 gallons 30# crosslink gel, 450000# 20-40 Brady sand & 50000# 20-40 resin coated sand. Shut well in.
4-18-96 - TIH & tagged sand at 1450'. Circulated sand to 1760' (310'). TOOH. Released

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Production Clerk DATE 4-24-96
TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY TIM W. GUM
DISTRICT II SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

APR 30 1996