Form 3160-5 (June 1990)

Subsequent Report

Final Abandonment Notice

N.M. Oil Cons. Divis UNITED STATES DEPARTMENT OF THE INTERIORS. 1st Street BUREAU OF LAND MANAGEMPICIA, NM 88210-2834

PUKAL APPROYED								
Budget Bur	cau No.	1004	-013:					
Expires:	March	31, 8	19 3					

5. Lease Designation and Serial No.

•		Dark man		301 W	
	10	1294	7-		

Non-Routine Fracturing Water Shut-Off

Conversion to Injection

SUNDRY NOTICES AND REPORTS ON WELLS C0279200 6. If Indian, Allottee or Tribe Name Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT-" for such proposals 7. If Unit or CA, Agreement Designation SUBMIT IN TRIPLICATE I. Type of Well Oil Well X Gas 8. Well Name and No. OXY Parther Federal #1 OXY USA Inc. 9. API Well No. 3. Address and Telephone No. DIST. 2 30-015-29142 P.O. Box 50250 Midland, TX 10. Field and Pool, or Exploratory Area 79710-0250 915-685-5717 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Morrow Gos Pool 11. County or Parish, State 1830 FSL 2130 FWL NESW(K) Sec 53 7175 R31E Edy NM CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Change of Plans Recompletion **New Construction**

Completion or Recompletion Report and Log form.) 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Plugging Back

See other side

ACCEPTED FOR RECORD OCT 1 7 1996 (ORIG. SGD.) GARY GOURLEY BLM

14. I hereby certify that the foregoing is true and correct David Stewart Regulatory Analyst (This space for Federal or State office use) Title

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements

ATTACHMENT 3160-5 OXY USA INC. OXY PANTHER FEDERAL #1 SEC 33 T178 R31E EDDY COUNTY, NM

NOTIFIED BLM 9/18/96 OF SPUD DATE & TIME. MIRU NABORS #967, SPUD WELL @ 1100hrs MDT 9/19/96. DRILL 17-1/2" HOLE TO TD @ 411', CHC. RIH W/ 13-3/8" 48# CSG & SET @ 393'. M&P 200sx CL H W/ 10% A11 + 10#/sx GILSONITE + 1% CaCl2 FOLLOWED BY 220sx BJ LITE W/ 2% CACL2 + .25#/sx CELLO-SEAL FOLLOWED BY 200sx CL C W/ 2% CaCl2, DISP W/ FW, PLUG DOWN @ 0200hrs MDT 9/19/96, NO RETURNS DURING CEMENT JOB, WOC-3hrs. BLM NOTIFIED BUT DID NOT WITNESS. RIH W/ 1" TBG & TAG CMT, M&P 110sx CL C NEAT, CIRC 13sx TO PIT, WOC. BLM NOTIFIED BUT DID NOT WITNESS. CUT OFF CASING, WELD ON STARTING HEAD, NU BOP & TEST TO 1000#, HELD OK. RIH, TAG CMT & DRILL AHEAD.

9/23/96, SUBMIT 3160-5 TO CHANGE INTERMEDIATE TD & CASING POINT. RECEIVED VERBAL APPROVAL FROM ADAM SALAMEH-BLM TO CHANGE TD & TO RUN DV TOOL & CASING PACKER, DUE TO LOST CIRCULATION.

DRILL 11" HOLE TO TD @ 3018', 9/25/96, CHC. RIH W/ GR/CAL, LOG FROM TD TO SURFACE, HOLE SEVERLY WASHED OUT FROM 1780-750' & 660-420', 23" CALIPER OFF SCALE. RIH W/ 8-5/8" 24-32# CSG & SET ACP @ 681', DV TOOL @ 664' & CSG @ 3018'. M&P 1400sx 65/35 C/POZ W/ 6% GEL + 5#/sx SALT + .25#/sx CELLOFLAKE + 10#/sx GILSONITE FOLLOWED BY 200sx CL C W/ 2% CACL2, DISP W/ FW, BUMP PLUG & SET ACP W/ 1700#, DROP BOMP & OPEN DV TOOL, ATTEMPT TO EST CIRC, W/O SUCCESS. CEMENT 2nd STAGE W/ 200sx CL H W/ 10#/sx GILSONITE + .25#/sx CELLOFLAKE + 1% CaCl2 + 10#/sx A11 FOLLOWED BY 250sx CL C W/ 65/35 C/POZ W/ 10#/sx GILSONITE + 5#/sx SALT + .25#/sx CELLOFLAKE, DISP W/ FW, BUMP PLUG @ 0830hrs mst 9/26/96 W/ 1550#. CEMENT DID NOT CIRCULATE, WOC. BLM NOTIFIED BUT DID NOT WITNESS. RIH W/ 1" TBG & TAG CMT @ 617', CEMENT W/ 100sx CL C W/ 6% CaCl2, TOH, WOC. RIH W/ 1" TBG & TAG CMT @ 440', CEMENT W/ 50sx CL C W/ 6% CaCl2, TOH, WOC. RIH W/ 1" TBG & TAG CMT @ 378', CEMENT W/ 110sx CL C W/ 6% CaCl2, TOH, WOC. RIH W/ 1" TBG & TAG CMT @ 200', CEMENT W/ 100sx CL C W/ 6% CaCl2, CIRC 10sx CMT TO PIT, TOH, WOC. ND BOP, SET SLIPS & CUT CSG. NOTIFY BLM OF BOP TEST, BUT DID NOT WITNESS, NU BOP & TEST TO 5000#, HELD OK. RIH & TAG CMT, TEST CSG TO 1000#, HELD OK, DRILL AHEAD.