Form 3160-5 (November 1983) (Formerly 9-331)

## UNITED STATES DEPARTMENT OF THE INTERIOR

SUBMIT IN TRIPLICATE \*
(Other Instructions on reverse side)

Budget Bureau No. 1004-0135 Expires August 31, 1985

,	Lit
()	1 1
	A Comment
	i€γ

DEPARTMENT OF THE INTERIOR  RUBEAU OF LAND MANAGEMENT			5. LEASE DESIGNATION AND SERIAL NO. LC-029419-B	
SUNDRY NOT	ICES AND REPORTS (	La Ministra de la Companya de la Ministra de la Companya del Companya de la Compa	6. IF INDIAN, ALLOTTEE OR TRI	BE NAME
1		<b>11 S. 18t Street</b> I <b>rtesia, NM 882</b> 10-2834	7. UNIT AGREEMENT NAME Skelly Unit	
2. NAME OF OPERATOR The Wiser Oil Company		n e donazione e e e e e e e e e e e e e e e e e e	8. API WELL NO. 30-015-29209	
3. ADDRESS OF OPERATOR	Name Marriage 00041		9. WELL NO. 265	
P. O. Box 2568 Hobbs, New Mexico 88241  4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)  At surface 158' FNL & 1438' FEL Sec. 27-T17S-R31E			10. FIELD AND POOL, OR WILDCAT Grayburg Jackson 7-Rivers 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA	
Unit B			Sec. 27-T17S-R31E	
14. PERMIT NO	15. ELEVATIONS (Show whether D 3826'	OF, RT, GR, etc.)	12. COUNTY OR PARISH Eddy	13. STATE NM
16. Check A	Appropriate Box to indicate Na	ture of Notice, Report, or Othe	er Data	
			BSEQUENT REPORT OF:	
TEST WATER SHUT OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL	
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING	·
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	G ABANDONMENT *	
REPAIR WELL (Other)	CHANGE PLANS	(Note: Report results of Completion or Recom	ting Cond., Surf. & Prod. Casin of multiple completion on Well apletion Report and Log form.)	
17. DESCRIBE PROPOSED OR COMPLET proposed work. If well is directionally	drilled, give subsurface locations and m	pertinent details, and give pertinent date leasured and true vertical depths for all	s, including estimated date of starting an markers and zones pertinent to this work	··)
MIRU Norton Drilling Co., R 10 jts. 8-5/8", 23#, ISW-42 S Flocele + 2% CaCl. Plug dov present. NU BOP & tested cs	T& C csg. Set at 443'. Ha wn @ 12:30 a.m, 11/05/96.	Illiburton cemented with 325. Circulated 51 sx. cmt. BL	Sx. Class "C" containing 1/ LM was notified, no represer	4#/SK.
Drilled 7-7/8" production hole at 3950'. Halliburton cement followed by 250 sxs. Premium MSA + 78 bbls. FW w/Lo-Su for 30 minutes, no pressure le	ted w/1000 gals. Superflush n Plus w/3#KCL/sk. + .5% l urf 300. Plug down at 6:45 a	102 + 900 sx. Halliburton L Halad 344 + 1/4# Flocele/sk am. 11/10/96. Circ. 119 sx	Lite + 8# salt/sk. + 1/4# Floce  Lite + 8# salt/sk. + 1/4# Floce	ele/sk. 2 bbls. g to 1500#
18 Thereby certify that the foregoing is true ar	nd correct.			
SIGNED Many Jo Tunny	TITLE Drillir	ng Department	DATE November 1	<u>4, 1996</u>
(This space for Federal or State office use)	ACC	EPTED FOR RECORD		-
AFPROVED BY	TITLE (CR.C.	SCD.) DAVID R. GLASS	DATE	<u> </u>
	*See Instru	ction On Reverse Side		