## State of New Mexico Energy, Ainerals and Natural Resources Department

Form C·103	,
Revised 1-1-89	ĺ

to Appropriate District Office
DISTRICT

P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

P.O.	Box 2	088
2.1		. 07504

WELL API NO.	
30-015-29215	
5. Indicate Type of Lease STATE	FEE [X]
6. State Oil & Gas Lease No.	

1	30-015-29215					
DISTRICT II P.O. Drawer DD, Artesia, NM 88210  Santa Fe, New Mexico 87504-2088	5. Indicate Type of Lease STATE FEE [X]					
DISTRICT III	6. State Oil & Gas Lease No.					
1000 Rio Brazos Rd., Aztec, NM 87410	N/A					
SUNDRY NOTICES AND REPORTS ON WELLS						
( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO	7. Lease Name or Unit Agreement Name					
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"						
(FORM C-101) FOR SUCH PROPOSALS.)	Ballard Grayburg					
1. Type of Well:	San Andres Unit					
OIL X OAS WELL OTHER	Tract #25					
2. Name of Operator	8. Well No.					
Anadarko Petroleum Corporation 000817	5					
3. Address of Operator	9. Pool name or Wildcat 39520					
PO Box 37, Loco Hills, NM 88255	Loco Hills Qn GB SA					
4. Well Location						
Unit Letter I : 2625 Feet From The South Line and	1200 Feet From The East Line					
Unil Letter : 2020 Feet From The 304011 Line and	Tea from the					
Section 5 Township 18S Range 29E	NMPM Eddy County					
Section 5 Township 105 Range 25E						
//////////////////////////////////////	<i>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</i>					
	Panort or Other Data					
11. Check Appropriate Box to Indicate Nature of Notice,						
NOTICE OF INTENTION TO:	JBSEQUENT REPORT OF:					
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING					
	ING OPNS. PLUG AND ABANDONMENT					
TEMPORARILY ABANDON L CHANGE PLANS L COMMENCE DRILL	ING OPNS PLUG AND ABANDONMENT L					
PULL OR ALTER CASING CASING TEST AND	CEMENT YOR					
OTHER: OTHER: CO-mi	OTHER: Co-mingle SA & GB Zone X					
12. Describe Proposed or Completed Operations (Clearly state all persinent details, and give pertinent dates, in work) SEE RULE 1103.	icluding estimated date of starting any proposed					
1. RUPU. TOH with production string.						
2. TIH with RBP latch on tool. Wash Frac sand from well. Latch onto RBP. TOH with RBP.						
	Poran production string Set SN & 3145' KB. POP 6-14-97					

4. RDPU.

- mm. Field Foreman DATE 06-23-97 Jacket Hackett SIONATURE -505/677-2411 TELEPTIONE NO. TYPE OR PRINT NAME

(This space for State Use)

JUL ... DATE -

CONDITIONS OF AFTROVAL, IF ANY: