

30-015-29443

C 30712 962

P 30712 80586

P 30712 2258

9.8.47

Camp Neutron

100'-3614'

Dual Lot.

2600'-3614'

Stemma Ray

2642'-3624'

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-015-29443
Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
State Oil & Gas Lease No. 20586
Lease Name or Unit Agreement Name Martin
Well No. 2
Pool name or Wildcat Atoka; Glorieta-Yeso

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
Name of Operator Arch Petroleum Inc.	
Address of Operator P. O. Box 10340, Midland, TX 79702-7340	
Well Location Unit Letter N : 330 Feet From The South Line and 2310 Feet From The West Line Section 23 Township 18S Range 26E NMPM Eddy County	
Elevation (Show whether DF, RKB, RT, GR, etc.) 3308' GR	

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ANBANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Arch Petroleum Inc. request permission to P&A the above captioned well. Well is uneconomical to produce.

Procedure:

1. POH & LD R X P.
2. POH w/ tbg.
3. RIH OE tbg & spot 100' cmt plug 2811'-2711'. Min. Cement Plug 25 ss. TAG
4. POH w/ tbg to 1050'. Spot cmt plug 1050'-925'. TAG
5. POH w/ tbg & spot 30' plug at surface.
6. Cut WH off 3' below GL & weld on plate & dry hole marker.

* All Cement Plugs Min. 25ss.

Brine Gel between all Plugs.

Notice N.M.O.C.D. to witness Plugging operations.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Cathy Tomberlin TITLE Operation Tech DATE 05-29-01
TYPE OR PRINT NAME Cathy Tomberlin TELEPHONE NO. 915-685-8100

(This space for State Use)

APPROVED BY Mike Stapp TITLE Envir. Eng. Spec. I DATE 7/11/2001
CONDITIONS OF APPROVAL, IF ANY:

