Form 3160-5 (November 1983) (Formerly 9-331)

UNITED STATES **DEPARTMENT OF THE INTERIOR**

SUBMIT IN TRIPLICATE * (Other Instructions on

Budget Bureau No. 1004-0135
Expires August 31, 1985

BUREAU	J OF LAND MANAGEMENT	reverse side)		
			5. LEASE DESIGNATION AND SE	RIAL NO.
SUNDRY NOTICES AND REPORTS ON WELLS			I.C-029418-B 6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
(Do not use this form for pro	posals to drill or to deepen or plug back to CATION FOR PERMIT - "for such propose	Marter and Heservoir. DIVISI		BE NAME
1.	4.1	1 2 191 p. ar.	7. UNIT AGREEMENT NAME	
OIL GAS	OTHER	ta∍a. Nivi ⊝3210-283	Lea "D"	
2. NAME OF OPERATOR			8. API WELL NO.	
The Wiser Oil Company			30-015-29702	
3. ADDRESS OF OPERATOR P.O. Box 2568 Hobbs, N	9. WELL NO. 22			
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.			10. FIELD AND POOL, OR WILDCAT	
See also space 17 helow.) At surface			Grayburg Jackson 7-Rivers	
At surface 1330' FNL & 2615' FWL Sec. 26-T17S-P31F			11. SEC., T., R., M., OR BLK. AND	
560. 20-1176-KG1E			SURVEY OR AREA	
Unit F	Sec. 26-T17S-R31E			
14. PERMIT NO	15. ELEVATIONS (Show whether DF, I 3837'	RT, GR, etc.)	12. COUNTY OR PARISH Eddy	13. STATE NM
16. Check	Appropriate Box to indicate Natur	e of Notice, Report, or Othe		1,1172
NOTICE OF INTENTION TO:			SEQUENT REPORT OF:	
TEST WATER SHUT OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL	
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING	
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT *	
			ADANDONMENT	
REPAIR WELL	CHANGE PLANS	(Other) Perforate, Acid		
			multiple completion on Well	
(Other) Completion or Recompletion Report and Log form.) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS: (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any				
proposed work. If well is directionally of	trilled, give subsurface locations and measur	red and true vertical depths for all ma	arkers and zones pertinent to this work.)	•
12/12/97 HES perforated San Andres Upper Jackson f/3867', 73', 77', 78', 79', 88', 89', 90', 98', 99', 3900', 09'-15' & 19'-23' w/1 SPF (23 holes). RIH w/5-1/2" Baker pkr. on 2-7/8" tbg. Set pkr. @ 3749'. HES acidized San Andres Upper Jackson perfs. 3867'-3923' w/4000 gals. 15% NE-FE acid + 56 ball scalers. Formation broke @ 3084#. ATP 1700# @ 4.1 bpm. MTP 3000# @ 4.2 bpm. Balled out w/5210#. ISIP 2016#. 5 min. 1942#. 10 min. 1896#. 15 min. 1873#.				
RBP and pkr. on 2-7/8" tbg. Se	un Andres Vacuum f/3728', 29', 30', 32', 30 t RBP @ 3855'. Acidized San Andres Vacu opm. MTP 3253# @ 6.1 bpm. Did not ball	um perfs. 3728'-3840' w/2500 gals	1. 15% NE-FE acid + 82 ball sealers. For	rmation broke
12/15/97 POH & LD tbg. ND BO.P. Install frac valve. HES frac'd San Andres Vacuum perfs. 3728'-3840' w/9000 gals. gel water, 17,360 gals. # 20 Delta Frac + 40,400# 16/30 Brady sand. ATP 2700# @ 32 bpm. MTP 3200# @ 33 bpm. ISIP 1972#. 5 min. 1884#. 10 min. 1854#. 15 min. 1845#.				
12/18/97 HES ran gauge ring to 3600' and stuck. Pulled out of rope socket. Left gauge ring in hole.				
12/19/97 Removed frac valve. NU BOP.	RIH w/20 jts. 2-7/8" tbg. w/overshot.			
12/20/97 RIH w/overshot to 3686'. Circa	ulated hole. Washed over fish @ 3787'. Pu	lled 5 jts. 2-7/8" tbg.		
18. I hereby certify that the foregoing is true as	nd correct.			
SIGNED Mary Go Turry	TITLE Completion	n Department	DATE <u>February 20, 1998</u>	
(This space for Federal or State office use)	ACCEPT	ED FOR RECORD		
APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	TITLE (ORIG. S	R 2 8 STOR GLASS	DATE	···········
	*See Instruction	On Reverse Side		